

# QUOTATION

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

## HONDA

H MOTOR CO. SDN. BHD.

(Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**Customer** : ERGO INSURANCE PTE LTD  
5 TEMASEK BOULEVARD  
#04-05 OSUNTEC TOWER FIVE  
SINGAPORE 038985

**Registration No** : SME6618Z

**Chassis No** : MRHFC5650JT001386

**Model** : CIVIC 1.6 VTI YM2018

**Owner's Name** : NG HOCK CHYE

**Ins Policy No.** :

**Date of Accident** : 28/11/2020

**Document No.** : SQT20003923  
**Date** : 3. Dec 2020  
**Customer No.** : WZN004  
**Svc Advisor** : IVAN TEO BOON KIAT  
**Engine No** : R16B25501623  
**Date | Time** : 3. Dec 2020 2:36:37 PM  
**Surveyor Name** :  
**Survey Date** :  
**Authorisation Date** :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST	Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: )							
	OWNER: NG HOCK CHYE							
	OWNER INSURER: FWD							
	ACC DATE: 28/11/2020							
	SURVEYED BY:							
	DATE:							
	REF NO:							
	TP INSURER: ERGO							
	TP VEH: GBK1876B							
71101-TEA-T50ZA	FACE,FR.BUMPER <i>Re-</i>	1	579.90	25	434.92	30.44	465.36	
71102-TBA-A10	GRILLEFR.BUMPER LOWER <i>X8U</i>	1	39.50	25	29.62	2.07	31.69	
71103-TEA-T00	GARNISHR.FR.BUMPER SIDE <i>sun</i>	1	19.70	15.60	14.77	1.03	15.80	
71130-TEA-T00	BEAM COMPFR.BUMPER <i>3Xn</i>	1	377.90	25	283.42	19.84	303.26	
71140-TEA-T00	BEAMR.FR.BUMPER UPPER <i>3Xn</i>	1	29.10	25	21.82	1.53	23.35	
71150-TEA-T00	BEAM COMPFR.BUMPER CENTER UPP <i>Xn</i>	1	234.70	25	176.02	12.32	188.34	
71193-TEA-T01	SPACERR.FR.BUMPER SIDE <i>n</i>	1	10.40	25	7.80	0.55	8.35	
71198-TEA-T01	SPACERL.FR.BUMPER SIDE <i>Xn</i>	1	10.40	25	7.80	0.55	8.35	
91505-TM8-003	CLIP,BUMPER <i>n</i>	16	2.30	25	27.60	1.93	29.53	
71121-TEA-T02	BASE,FR.GRILLE CHROME <i>?on</i>	1	80.60	25	60.45	4.23	64.68	
71125-TEA-T01	MOLDINGFR.GRILLE <i>X-Xn</i>	1	109.70	25	82.27	5.76	88.03	
71124-TEA-T01	EXTENSION ASSYR.FR.GRILLE <i>?Xn</i>	1	93.60	25	70.20	4.91	75.11	
75700-TBA-A00	EMBLEM <i>n</i>	1	16.40	25	12.30	0.86	13.16	
90301-ST0-003	NUTPUSH 3MM <i>n</i>	2	2.10	25	3.15	0.22	3.37	
60211-TBA-A00ZZ	PANELR.FENDER <i>repw</i>	1	450.80	25	338.10	23.67	361.77	
74101-TEA-T00	FENDERR.FR.INNER <i>Xn</i>	1	55.80	25	41.85	2.93	44.78	
33100-TEC-Q01	HEADLIGHT ASSY,R. <i>?Xn</i>	1	639.90	25	479.92	33.59	513.51	
					<b>Sum Item</b>	<b>2092.01</b>	<b>146.43</b>	<b>2,238.44</b>

Printed on 3/12/2020 2:47:37 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**HONDA****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

<b>Customer</b>	: ERGO INSURANCE PTE LTD 5 TEMASEK BOULEVARD #04-05 OSUNTEC TOWER FIVE SINGAPORE 038985	<b>Document No.</b>	: SQT20003923	<b>Page</b>	2
<b>Registration No</b>	: SME6618Z	<b>Date</b>	: 3. Dec 2020		
<b>Chassis No</b>	: MRHFC5650JT001386	<b>Customer No.</b>	: WZN004		
<b>Model</b>	: CIVIC 1.6 VTI YM2018	<b>Svc Advisor</b>	: IVAN TEO BOON KIAT		
<b>Owner's Name</b>	: NG HOCK CHYE	<b>Engine No</b>	: R16B25501623		
<b>Ins Policy No.</b>	:	<b>Date   Time</b>	: 3. Dec 2020 2:36:37 PM		
<b>Date of Accident</b>	: 28/11/2020	<b>Surveyor Name</b>	:		
		<b>Survey Date</b>	:		
		<b>Authorisation Date</b>	:		

<b>Item</b>	<b>Description</b>	<b>Qty</b>	<b>Unit Price</b>	<b>Disc %</b>	<b>Amount</b>	<b>0% GST Amount</b>	<b>Amount incld GST</b>
BOSUN	SUNDRIES	1	100.00	30 /	100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	280.00	180 /	280.00	19.60	299.60
BKBU01R	REMOVE & RENEW FR BUMPER INCLUDING FITTINGS ON	1	2600.00	1300 /	2600.00	182.00	2782.00
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	2000.00	1040 /	2080.00	145.60	2225.60
					<b>Sum Labor</b>	<b>5060.00</b>	<b>354.20</b>
							<b>5,414.20</b>

<b>Survey By</b>	<u>RASUL - 14090010068</u>					
<b>Date &amp; Time</b>	<u>07/12/2020 @1445</u>		<b>Total Amount</b>	7,152.01	500.63	7,652.64
<b>Excess</b>		<b>Total (Inclusive of GST)</b>				<b>7,652.64</b>
<b>Status</b>						
<b>Signature</b>	<u>Rasul</u>	<i>5 days</i>				<b>7190.86</b>
		<i>Resy before paint</i>				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 3/12/2020 2:47:37 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.