



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGN 3908E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	REPLACED	1,425.00	1,425.00
1	FRONT BUMPER LICENSE BRACKET	REPLACED	165.00	165.00
2	FRONT BUMPER SIDE RETAINER	REPLACED	36.00	36.00
1	FRONT BUMPER TOW COVER	REPLACED	72.00	72.00
1	FRONT BUMPER SIDE GUARD LH	NOT NECESSARY	64.00	-
1	FRONT BUMPER SIDE GUARD RH	REPLACED	64.00	64.00
1	FRONT BUMPER CENTRE SPONGE	NOT NECESSARY	100.00	-
1	FRONT BUMPER SIDE SPONGE LH	NOT NECESSARY	50.00	-
1	FRONT BUMPER SIDE SPONGE RH	NOT NECESSARY	50.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	455.00	-
1	FRONT HEADLAMP RH	NOT NECESSARY	3,150.00	-
1	FRONT HEADLAMP LH	NOT NECESSARY	3,150.00	-
1	FRONT GRILLE ASSY	NOT NECESSARY	1,075.00	-
1	FRONT GRILLE EMBLEM	NOT NECESSARY	40.00	-
	LESS 10% DISCOUNT		-989.60	-176.20
			8,906.40	1,585.80
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT BUMPER CLIP (SN)	REPLACED	30.00	30.00
1	SET FRONT GRILLE CLIP (SN)	NOT NECESSARY	20.00	-
1	FRONT NUMBER PLATE (SN)	REPLACED	80.00	45.00
			130.00	75.00
	<b><u>LABOUR</u></b>			
	CHECK FRONT WIRING AND LIGHTING SYSTEM.		60.00	30.00
	PANEL BEATING ON AFFECTED AREAS.		600.00	250.00
	SPRAY PAINTING ON AFFECTED AREAS.		700.00	250.00
	APPLY ANTI RUST ON AFFECTED AREAS.	NOT NECESSARY	80.00	-
			1,440.00	530.00
	<b>GRAND TOTAL</b>		<b>10,476.40</b>	<b>2,190.80</b>

Report Ref No. CS/GAI20013315/T1vf3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,750.00
---	--	--	----------

Report Ref No. CS/GAI20013315/T1vf3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.