

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | Reg. No: 199607198R GST Reg. No. 19-9607198-R | | | | |
|-------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-----------------|------------------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
| | GREAT AMERICA | N INSURANCE COMPANY | Ref: | CS/GAI20013315/T1vf3q2 | |
| | 3 TEMASEK AVEN #16-01 CENTENN SINGAPORE 0391 | IAL TOWER | Date: | 17/02/2021 | |
| | | | Code | GAI | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION) | | | | |
| | Insured Veh. | GBJ 4423K | Veh. Inspected | SGN 3908E | |
| | Policy No. | | Coverage (\$) | 0.00 | |
| | Claim No. | CLMOMVC000003884 | Excess (\$) | 0.00 | |
| | Assign From | ELIZBETH CHEW | Assign Date | 03/12/2020 | |
| 2. | . Vehicle Particulars & Condition | | | | |
| | Make & Model | MERCEDES BENZ C180 | c.c | 1796 | |
| | Engine No. | HIDDEN | Year of Reg. | 2006 | |
| | Chassis No. | WDC2030462R246914 | Colour | SILVER | |
| | Odometer | - | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | SPORTS RIM | |
| | General | GOOD | | | |
| 3. | Conditions of Tyres | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 195/65 R15 | BRIDGESTONE | 6 mm | |
| | L/H Front Tyre | 195/65 R15 | BRIDGESTONE | 6 mm | |
| | R/H Rear Tyre | 195/65 R15 | BRIDGESTONE | 6 mm | |
| | L/H Rear Tyre | 195/65 R15 | BRIDGESTONE | 6 mm | |
| 4. | Description of Damages | | | | |
| | THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. | | | | |
| | REPAIR CONDITION SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 22/08/2020 | Inspection Date | 21/01/2021 | |
| | Survey held at | GREEN STAR SPRAY PAINTIN | G | | |
| | | BLK 3011 BEDOK NORTH AVE 4 #01-2004 BEDOK INDUSTRIAL PARK E SINGAPORE 489977 | | | |
| 5a. | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | b. Estimate Days of Repair | | | | |

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: