

ASS. REC. BY:

Taylth

REF:

CS/GA/20013315/T.1 of 3

ASSIGNMENT

COE 2026 Nov

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGN 3908E Yr Regn: 2006 / NovType: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz C180 c.c. 1796Colour: 8/100 A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDC2030462R246914

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 22/8/20

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 21/1/2009 9:15am

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.A. / _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

3RD PARTY CLAIM ESTIMATION

Vehicle number	:	SGN3908E
Make / Model	:	
Chassis number	:	WDC2030462R246914
Accident date	:	
Reference	:	

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER	1425.00 <i>de✓</i>
1	FRONT BUMPER LICENSE BRACKET	165.00 <i>de✓</i>
2	FRONT BUMPER SIDE RETAINER	36.00 <i>nei✓</i>
1	FRONT BUMPER TOW COVER	72.00 <i>ent✓</i>
1	FRONT BUMPER SIDE GUARD LH	64.00 <i>x nn</i>
1	FRONT BUMPER SIDE GUARD RH	64.00 <i>de✓</i>
1	FRONT BUMPER CENTRE SPONGE	100.00 <i>x</i>
1	FRONT BUMPER SIDE SPONGE LH	50.00 <i>x</i>
1	FRONT BUMPER SIDE SPOINGE RH	50.00 <i>x</i>
1	FRONT BUMPER REINFORCMENT	455.00 <i>x</i>
1	FRONT HEADLAMP RH	3150.00 <i>x</i>
1	FRONT HEADLAMP LH	3150.00 <i>x</i>
1	FRONT GRILLE ASSY	1075.00 <i>x</i>
1	FRONT GRILLE EMBLEM	40.00 <i>x</i>
		1762
	Less 10%	1585.80
	Subtotal	8906.40
	Balance C/F	8906.40
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1 SET	FRONT BUMPER CLIP	30.00 <i>nei✓</i>
1 SET	FRONT GRILLE CLIP	20.00 <i>x nn</i>
1	FRONT NUMBER PLATE	80.00 <i>45 mis✓</i>
	Subtotal	130.00 <i>75</i>
	Balance C/F	9036.40
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	9036.40
1	CHECK FRONT WIRING AND LIGHTING SYSTEM	60.00 <i>30</i>
2	PANEL BEATING ON AFFECTED AREAS	600.00 <i>250</i>
3	SPRAY PAINTING ON AFFECTED AREAS	700.00 <i>250</i>
4	APPLY ANTI RUST ON AFFECTED AREAS	80.00 <i>x nn</i>
	Subtotal	1440.00 <i>530</i>
	Grand total	10476.40

1585.80
75
530
\$2190.80
4581750#

3 days