



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO20013319/Uqd3q2	
			Date: 05/01/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBR 2328Z	Veh. Inspected	SMJ 7517Z
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2003503/AGC	Excess (\$)	0.00
	Assign From	MELVIN YE YONG	Assign Date	03/12/2020
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 6 (A)	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	JM6GL1072K0313769	Colour	GREY
	Odometer	59132 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/55 R17	BRIDGESTONE	6 mm
	L/H Front Tyre	225/55 R17	BRIDGESTONE	6 mm
	R/H Rear Tyre	225/55 R17	BRIDGESTONE	6 mm
	L/H Rear Tyre	225/55 R17	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/11/2020	Inspection Date	04/12/2020
	Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	