

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0935/2020/NS
DATE : 30-Nov-20
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian

3 days - ok - jb - 20 Jan 20

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR REYJAL FABIEN ALEXANDRE
ADDRESS : 8 LEEDON HEIGHTS
#08-06
SINGAPORE 2662156
TELEPHONE : HP +65 91116248
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100470715-04
VEHICLE NO : **SLD 3865 M**
MODEL CODE : AUDI A3 SPORTSBACK 1.4 TFSI
MODEL YEAR : 15/6/2016
ENGINE NO : CZC 521901
CHASSIS NO : WAUZZZ8V4GA106079
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-Nov-20
PLACE OF ACCIDENT : SHANGRI LA HOTEL GRANGE ROAD

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLD 3865 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	\$ 500.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$ 2,000.00	\$ 550.00
5	TO CARRY OUT DISGNOCTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 4,922.00	\$ 1,242.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 3865 M

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT		REMARKS
1	FRONT BUMPER		\$ 1,842.00	\$	1,473.60
2	FRONT BUMPER FIXING PARTS		\$ 185.00		
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 154.00	\$	123.20
4	FRONT BUMPER PULL STRAP - LOWER	4	\$ 204.00	\$	162.88
5	FRONT BUMPER AIR GUIDE GRILLE - LH		\$ 108.00		
6	RADIATOR GRILLE		\$ 683.00	\$	546.40
7	RADIATOR GRILLE COVER		\$ 97.00		
8	CAUTION SIGN STICKER	NEC	\$ 14.00	\$	10.80
9	AIRCON STICKER	NEC	\$ 8.00	\$	5.68
10	FRONT REINFORCEMENT BEAM		\$ 715.00		
11	FRONT BUMPER FOAM FILLER PIECE		\$ 82.00		
12	FOAM FILLER PIECE COVER		\$ 55.00		
13	RADIATOR AIR GUIDE - LH		\$ 24.00		
14	FRONT BUMPER NOISE INSULATION		\$ 264.00		
15	WHEEL HOUSING LINER - LH		\$ 167.00	\$	133.20
16	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 88.00		
17	LIFT CYLINDER - LH		\$ 190.00		
18	FRONT FENDER - LH		\$ 841.00		
19	FRONT FENDER ATTACHMENT PARTS		\$ 71.00		
20	FRONT FENDER CLOSING ELEMENT		\$ 61.00		
21	FRONT FENDER BRACKET - LH		\$ 47.00		
22	FRONT FENDER BRACE		\$ 95.00		
23	FRONT NO PLATE	S/N	\$ 60.00	\$	60.00
24	SUNDRIES		\$ 200.00		
TOTAL SPARE PARTS		:	\$ 6,255.00	\$	2,515.76
TOTAL LABOUR CHARGES		:	\$ 4,922.00	\$	1,242.00
GRAND TOTAL		:	\$ 11,177.00	\$	3,757.76

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LAOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT