

Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

30 NOV 2020

E S T I M A T E

Estimate No. : b1 56698
Date Estimated : 30/11/2020
Prepared By : Chua Kee Sin

Page No. : 1 of 7

- ESTIMATE REPAIR FOR -
Tan Teck Ching (Chen Dixin)
311C Clementi Avenue 4
#14-191

Singapore 123311

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN2953X	WBA2E320605H46190	28/04/2017	216d G TOURER	0

DESCRIPTIONVALUE

Rear rear floor pan, tail end panel, boot lid, rear bumper include removing attachment et c and repair on the accident damage area	6800	9,350.00
(2) Spray painting rear floor pan, tail end panel, both rear side fender, rear boot lid and rear bumper	4470	4,987.00
To replace rear windscreen gla ss.		676.00
To conduct water leak tests.		75.00
To supply and install rear windscreen solar film.		531.00
To check electrical wiring sys tem and lighting at the rear s ection for proper function.	150	177.00
To replace rear exhaust silenc er including alignment system and conduct check for leak.	451	531.00
To carry out body cavitypreser vation. (For cut panel).	451	531.00
To carry out body cavitypreser vation. (Per panel).	100	118.00
To replace front centre exhaus t silencer including alignment and conduct checks for leak.	451?	531.00
To remove and install boot com partment carpet and garnish to facilitate repair.	230	271.00
To tow accident vehicle to PML workshop.		150.00
Being charge for LTA inspection fees.of breaking amd install no plate seal	?	160.00
Sundries	?	150.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 56698
Date Estimated : 30/11/2020
Prepared By : Chua Kee Sin

Page No. : 2 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN2953X	WBA2E320605H46190	28/04/2017	216d G TOURER	0

DESCRIPTION	VALUE
To supply rear emboss number plate - Red <i>re</i>	83.00

Total Labour 1: 18,301.00

DESCRIPTION	QTY	PRIC	VALUE
C CLIP FOR PLASTIC NUT ?	10	1.10	11.00
RUBBER MOUNTING	2	17.70	35.40
FRONT SILENCER ?	1	1,020.75	1,020.75
REAR SILENCER ?	1	1,010.00	1,010.00
TAILPIPE TRIM BLACK CHROME <i>SC</i>	1	112.20	112.20
HOLDER EXHAUST SYSTEM ?	2	58.65	117.30
BOOTLID <i>lt</i>	1	1,210.35	1,210.35
LH TRUNK LID HINGE ?	1	79.75	79.75
RH TRUNK LID HINGE ?	1	79.75	79.75
TRUNK FLOOR <i>blue</i>	1	581.30	581.30
INTERIOR TAIL TRIM ?	1	280.50	280.50
TAIL PANEL <i>lt</i>	1	357.00	357.00
REPAIR KIT GROUND STRAP ?	1	30.65	30.65
RR BUMPER LH SIDE GUIDE ?	1	61.35	61.35
RR BUMPER RH SIDE GUIDE ?	1	61.35	61.35
REAR BUMPER CARRIER <i>lt</i>	1	460.40	460.40
SUPPORT ?	1	45.55	45.55
RR BUMPER LH INNER SIDE GUIDE ?	1	61.35	61.35
RR BUMPER RH INNER SIDE GUIDE ?	1	61.35	61.35
REAR BUMPER TRIM STRIP (CHROM) <i>cm</i>	1	110.55	110.55
LEFT PROTECT ?	1	11.20	11.20
RIGHT PROTEC ?	1	11.20	11.20
REAR BUMPER PANEL PRIMED (LINES PDC <i>de</i>	1	1,045.45	1,045.45
SET MOUNTS PDC SENSOR REAR <i>re</i>	1	60.70	60.70
REAR BUMPER TOWING FLAP EYE PRIMED <i>sc</i>	1	43.05	43.05
LETTERING 216 D <i>re</i>	1	64.45	64.45
GROMMET <i>re</i>	2	0.80	1.60
PLAQUE 74MM <i>re</i>	1	71.60	71.60
STRIKER BOOT LID ?	1	59.80	59.80
LOCK TRUNK LID ?	1	194.75	194.75
ACTUATION UNIT ?	1	612.10	612.10
SPINDLE DRIVE - rear boot ?	2	355.65	711.30
Lock plate ?	1	12.40	12.40
BUMP STOP <i>re</i>	10	3.20	32.00
REAR WINDOW ?	1	657.60	657.60
HOOK AND LOOP FASTENER ?	4	2.85	11.40
LH UPHOLSTERY 3RD ROW SUPPORT ?	1	23.55	23.55
RH UPHOLSTERY 3RD ROW SUPPORT ?	1	23.55	23.55
3rd ROW LUGGAGE COMPARTMENT TRAY ?	1	126.90	126.90
Bodenverklei- floor trim 3tow ?	1	916.10	916.10
THERMAL PROTECTION LUGGAGE COMP. WE ?	1	58.30	58.30
LOADING SILL COVER (ANTHRAZIT) ?	1	79.55	79.55
LOADING SILL COVER (ANTHRAZIT) ?	1	79.55	79.55

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 56698
Date Estimated : 30/11/2020
Prepared By : Chua Kee Sin

Page No. : 3 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN2953X	WBA2E320605H46190	28/04/2017	216d G TOURER	0

DESCRIPTION	QTY	PRIC	VALUE
rear floor trim - rear seat ?	1	916.10	916.10
REAR BUMPER HEAT INSULATION ?	1	63.50	63.50
TRIM PANEL TAILGATE BOTTOM INNER (S ?	1	282.65	282.65
WARNING SIGNALLER ?	1	35.35	35.35
BOOTLID SEALING <i>me</i> ?	1	143.85	143.85
REAR LH REFLECTOR ?	1	38.85	38.85
REAR RH REFLECTOR <i>cm</i> ?	1	38.85	38.85
LH GUTTER STRIP ?	1	25.95	25.95
RH GUTTER STRIP ?	1	25.95	25.95
REAR LH LIGHT IN THE TRUNK LID ?	1	262.15	262.15
REAR RH LIGHT IN THE TRUNK LID ?	1	262.15	262.15
REAR LH LIGHT IN THE SIDE PANEL ?	1	374.45	374.45
REAR RH LIGHT IN THE SIDE PANEL ?	1	374.45	374.45
NUMBER-PLATE LIGHT LED ?	2	27.45	54.90
DECOUPING RING PDC TORQUE CONVERTER ?	4	5.10	20.40
ULTRASONIC SENSOR IMPERIALBLAU(WA89 ?	4	370.00	1,480.00
SET ADHESIVE PADS FOR ACE 2.0 <i>me</i> ?	1	43.65	43.65
BLIND RIVET AVIBVLB ?	43	0.55	23.65
BLIND RIVET AVIBVLB ?	23	0.55	12.65
BLIND RIVET AVIBVLB ?	20	0.55	11.00
SCREW (SF PLUS M5X15) ?	11	0.55	6.05
SCREW (SF PLUS M5X15) ?	5	0.55	2.75
SCREW (SF PLUS M5X15) ?	3	0.55	1.65
(DG/SL) BODY ADHESIVE K5B (195ML) <i>me</i> ?	1	331.80	331.80
(DG/SL) BODY ADHESIVE K5B (195ML) <i>me</i> ?	1	331.80	331.80
(DG) BODYWORK ADHESIVE K5A (50ML) <i>me</i> ?	1	114.45	114.45
(DG) BODYWORK ADHESIVE K5A (50ML) <i>me</i> ?	1	114.45	114.45
(DG) CLEANER R1 (100ML) <i>me</i> ?	1	26.15	26.15
(DG) CLEANER R1 (100ML) <i>me</i> ?	1	26.15	26.15
(DG) CLEANER R1 (100ML) <i>me</i> ?	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>me</i> ?	2	131.55	263.10
PUNCH RIVET N4 <i>me</i> ?	23	0.55	12.65
PUNCH RIVET N4 <i>me</i> ?	19	0.55	10.45
(DG/SL)ADHESIVE PRIMER VP 206 (30ML) <i>me</i> ?	1	27.85	27.85
(DG/SL)ADHESIVE PRIMER VP 206 (30ML) <i>me</i> ?	1	27.85	27.85
(S/L) SEAM SEAL 300ML <i>me</i> ?	1	33.80	33.80

Total Parts : 16,543.55

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 56698
Date Estimated : 30/11/2020
Prepared By : Chua Kee Sin

Page No. : 4 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN2953X	WBA2E320605H46190	28/04/2017	216d G TOURER	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 01/12/2020 @ 1120 Excess S\$ _____

Surveyor's Name Ryan Sign _____

Surveyor's Tel 90016068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 15 days



Labour 1	:	18,301.00
Parts	:	16,543.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,439.12
Grand Total	:	37,283.67

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **