



Final Report

Estimate No. : **b1 56698**
Date Estimated : **30/11/2020**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
Tan Teck Ching (Chen Dixin)
311C Clementi Avenue 4
#14-191

Singapore 123311

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN2953X	WBA2E320605H461	28/04/2017	216d G TOURER	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
Replace rear floor pan,tail end panel,boot lid,rear bumper,rear right chassis include removing attachment, and repair on the accident damage area	6,800.00	0.00	6,800.00	
Spray painting rear floor pan, tail end panel,both rear side fender,rear boot lid and rear bumper	4,470.00	0.00	4,470.00	
To transfer rear windscreen glass to new boot lid.	676.00	0.00	676.00	
To conduct water leak tests.	75.00	0.00	75.00	
To check electrical wiring sys tem and lighting at the rear section	150.00	0.00	150.00	
To replace rear exhaust silencer including alignment system.	451.00	0.00	451.00	
To carry out body cavitypreser vation. (For cut panel).	451.00	0.00	451.00	
To carry out body cavitypreser vation. (Per panel).	100.00	0.00	100.00	
To replace front centre exhaust silencer including alignment.	451.00	0.00	451.00	
Remove and install boot compartment carpet and garnish to facilitate repair.	230.00	0.00	230.00	
To tow accident vehicle to PML workshop.	150.00	0.00	150.00	
Being charge for LTA inspection fees.of breaking amd install no plate seal	160.00	0.00	160.00	
Sundries	150.00	0.00	150.00	
# TO Break and RESEAL NUMBER PLATE FEE	21.40	0.00	21.40	
# To mount vehicle on celette bench to facilitate re-alignment of body/chassis according to BMW specification	2,950.00	0.00	2,950.00	
DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# COARSE THREADED BOLT (L=14.2MM)	2.65	10.00	0.00	26.50



Final Report

# CLAMPING BUSH	54.60	1.00	0.00	54.60
FRONT SILENCER	1,025.85	1.00	0.00	1,025.85
REAR SILENCER	1,015.05	1.00	0.00	1,015.05
HOLDER EXHAUST SYSTEM	28.75	1.00	0.00	28.75
BOOTLID	1,174.04	1.00	0.00	1,174.04
TRUNK FLOOR	530.55	1.00	0.00	530.55
INTERIOR TAIL TRIM	280.50	1.00	0.00	280.50
TAIL PANEL	357.00	1.00	0.00	357.00
# EXPANDING NUT	1.00	2.00	0.00	2.00
REAR BUMPER CARRIER	446.59	1.00	0.00	446.59
SUPPORT	45.55	1.00	0.00	45.55
RR BUMPER LH INNER SIDE GUIDE	61.35	1.00	0.00	61.35
RR BUMPER RH INNER SIDE GUIDE	61.35	1.00	0.00	61.35
REAR BUMPER TRIM STRIP (CHROM)	110.55	1.00	0.00	110.55
REAR BUMPER PANEL PRIMED (LINES PDC	1,045.45	1.00	0.00	1,045.45
LETTERING 216 D	64.45	1.00	0.00	64.45
GROMMET	0.80	2.00	0.00	1.60
PLAQUE 74MM	71.60	1.00	0.00	71.60
3rd ROW LUGGAGE COMPARTMENT TRAY	126.90	1.00	0.00	126.90
THERMAL PROTECTION LUGGAGE COMP. WE	58.30	1.00	0.00	58.30
LOADING SILL COVER (ANTHRAZIT)	79.55	1.00	0.00	79.55
# (DG/SL) SOUND DEADENER 1160X700MM	83.65	1.00	0.00	83.65
REAR RH REFLECTOR	38.85	1.00	0.00	38.85
# SNAP LOCKING COUPLING	1.05	3.00	0.00	3.15
BLIND RIVET AVIBVLB	0.55	20.00	0.00	11.00
SCREW (SF PLUS M5X15)	0.55	3.00	0.00	1.65
(DG/SL) BODY ADHESIVE K5B (195ML)	336.75	1.00	0.00	336.75
(DG) BODYWORK ADHESIVE K5A (50ML)	116.15	1.00	0.00	116.15
(DG) CLEANER R1 (100ML)	26.15	1.00	0.00	26.15
(DG) CLEANER R1 (100ML)	26.15	1.00	0.00	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00	0.00	263.10
PUNCH RIVET N4	0.55	20.00	0.00	11.00
(DG/SL)ADHESIVE PRIMER VP 206 (30ML	27.85	1.00	0.00	27.85
(S/L) SEAM SEAL 300ML	33.80	1.00	0.00	33.80

SUPPLEMENTARY ITEMS

Total Labour :	17,285.40
Total Parts :	7,647.33
Total Labour & Parts :	24,932.73
Deduction for Excess :	
Total Repair Costs less Excess:	24,932.73
GST @7%:	1,745.29
Grand Total :	26,678.02

LOSS OF USE=\$100 X 24 DAYS



supplementary

Estimate No. : **b1 56698**
Date Estimated : **30/11/2020**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
Tan Teck Ching (Chen Dixin)
311C Clementi Avenue 4
#14-191

Singapore 123311

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN2953X	WBA2E320605H461	28/04/2017	216d G TOURER	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# TO Break and RESEAL NUMBER PLATE FEE	21.40	0.00	21.40
# To mount vehicle on celette bench to facilitate re-alignment of body/chassis according to BMW specification	2,950.00	0.00	2,950.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# COARSE THREADED BOLT (L=14.2MM)	2.65	10.00	0.00	26.50
# CLAMPING BUSH	54.60	1.00	0.00	54.60
# EXPANDING NUT	1.00	2.00	0.00	2.00
# (DG/SL) SOUND DEADENER 1160X700MM	83.65	1.00	0.00	83.65
# SNAP LOCKING COUPLING	1.05	3.00	0.00	3.15
#				

SUPPLEMENTARY ITEMS

Total Labour :	2,971.40
Total Parts :	169.90

STA Inspection Pte Ltd
302 Sin Ming Rd
Singapore 575627
Tel : 64521398

*** RECEIPT ***

CO REG NO : 198204973D
GST REG NO : M2-0058358-2
15-Jan-2021 2:25 pm

Receipt No. : CPO20003414660
Cashier : 60720225
Machine : CPO2
Cust Code : CASH
Customer : Walk-In
Vehicle No. : SLN2953X
Chassis NO. :
WBAZE320605H46190
Front Seal No :
Rear Seal No : 246862

Item	Amount
S&P	10.00
GST	0.70
Amount Due	10.70
CASH	10.70
TENDER	10.70
ROUNDING DIFF	0.00

THANK YOU
STRICTLY NO REFUND

STA Inspection Pte Ltd
302 Sin Ming Rd
Singapore 575627
Tel : 64521398

Duplicate Copy

*** RECEIPT ***

CO REG NO : 198204973D
GST REG NO : M2-0058358-2
22-Dec-2020 9:15 am

Receipt No. : CPO20003397829
Cashier : 60720225
Machine : CPO2
Cust Code : CASH
Customer : Walk-In
Vehicle No. : SLN2953X

Item	Amount
S-PIN	10.00
GST	0.70
Amount Due	10.70
CASH	10.70
TENDER	10.70
ROUNDING DIFF	0.00

THANK YOU
STRICTLY NO REFUND

10 Sin Ming Drive Singapore 575701
www.lta.gov.sg

22 Dec 2020

Our ref 2212200104N002017877

TAN TECK CHING (CHEN DIXIN)
APT BLK 311C CLEMENTI AVENUE 4
#14-191
SINGAPORE 123311

Dear Sir/Madam

**APPROVAL TO BREAK AND RESEAL NUMBER PLATE(S) OF REVISED OFF-PEAK
CAR: SLN2953X**

We refer to your application to break and reseal the number plate(s) for the above-mentioned vehicle.

2. Your application has been approved and you may proceed to remove the rear number plate(s) of the vehicle. Once the repair work or any other work on the vehicle is completed, you are required to refit the bracket(s) and number plate(s) and send the vehicle to any of the following vehicle inspection centres for inspection and sealing of the number plate(s) by **21 Jan 2021**:

- STA Inspection Pte Ltd
- JIC Inspection Services Pte Ltd
- VICOM Ltd

3. Please ensure that the number plate(s) is/are resealed by the date stated above. You are required to submit a fresh application with justifications and supporting documents (if any) to our office at LTA, 10 Sin Ming Drive, Singapore 575701, VRL Service Operations Division at least 1 working day before **21 Jan 2021** if you need more time to complete the work on the vehicle.

4. Please be advised that prior approval from the LTA must be obtained before breaking the seal and resealing the number plate(s) of the vehicle. It is a serious offence for any person, except a person authorised by the Registrar of Vehicles, to remove, break or tamper with a seal affixed on a vehicle without our prior approval. Any person convicted of the offence shall be liable with a fine not exceeding \$1,000 or imprisonment to a term not exceeding 3 months, and for the second or subsequent offences a fine not exceeding \$2,000 or imprisonment to a term not exceeding 6 months.



NUMBER PLATE SEALS INSPECTION CERTIFICATE

Serial No. S20210115001

Vehicle No. : SLN2953X	Make & Model : B.M.W. 216D GRAN TOURER LED NAV 7 SEATER
Seal No (Front) : 224275	Seal No (Rear) : 246862
Type of Inspection : REPLACEMENT	Chassis No. : WBA2E320605H46190

Inspection Items

Legend: P-Pass F-Fail NA-Not Applicable

Front Seal		Status	Rear Seal		Status
1	Number Plate	P	1	Number Plate	P
2	Bolt & Nut	P	2	Bolt & Nut	P
3	Brackets	P	3	Brackets	NA
4	Seal	P	4	Seal	P

RESULT

PASS

Remarks

REPLACEMENT SEAL (REAR) .

This is to certify that the number plates of the above motor vehicle were examined and found to comply with the prescribed statutory requirements.

The number plates were duly sealed.

Inspected By:

60720167

Chin Bee Teck

Date & Time Issued

15/01/2021

14:39

This is a computer-generated document. No signature is required.

For the purpose of renewing road tax, this Certificate must be presented within 3 months from the date of issue.