

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SKS2183L

Mazda 3

6BM42A860301356

TP ALG.

Cecilia.

Rees Buyer Debon d

1062.50 ✓

30(SN) ✓

Rees Buyer Clips. per

Rees Buyer Side Holder x 2 ^{HP} 35 x 2 = 70 +

Rees Buyer Reflector RH. ^{HP} 54.90 ✓

Rees Buyer Reinforcement. ^{HP} 491.80 ✓

List: 1609.20

Len 20%: 1287.36

S.N: 230

Labour: 680.

Reverse Sensor ^{HP} 280(SN) 200(SN)

Rees End Panel ^{HP} 559.60 +

Rees End Panel Top Garish ^{HP} 168 +

Rees End Panel Sealant. ^{HP} 60(SN) +

Rees End Panel Tuillap RH. ^{HP} 915. +

2/8/17K

03Days.

Panel Beating

Spray Painting.

Wiring

To remove reverse sensor

To spray tuft coat

To remove upholstery.

~~800~~ 300.

~~600~~ 300

~~50~~ 30

~~100~~ 50

150 X

150 X.