



Section A - Accident Details

Registration Number	SHD6269L
Case Reference Number	TAX/11/20/2057
Registration Date	26/12/2019
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	CHEONG KUT SHUN
Type of Accident	Head to Rear
Accident Date and Time	25/11/2020 7:50 PM
Accident Reported Date and Time	26/11/2020 2:59 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108945
Special Instruction to ARC, if any	TP /REAR PORTION/ AIG - LKK
Prepared Date and Time	26/11/2020 3:36 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$738.00	\$200.00
Total Spare Part Cost	\$2,647.68	\$425.63
Total Other Cost	\$600.00	\$60.00
TOTAL COST	\$4,492.68	\$885.63 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / AIG
ARC / Surveyor Sign Off Date	26/11/2020 3:52 PM	26/11/2020 4:43 PM
Signature		
Remarks		P/P, before paint photo

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2012-0073	Invoice Number	
Quotation Date	08.12.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$507.00	\$200.00
Total Labour	\$507.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$738.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE AND REFIT WIRE HARDESS	\$120.00	\$20.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$600.00	\$60.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$485.60	100.00	\$0.00	Replace	Repair	
		52462-47020	PAD, RR BUMPER, RH & LH, 1	0.00	\$4.00	0.00	\$0.00	Replace	Not Given	X SUC
		52462-47030	PAD, RR BUMPER, RH & LH, 2	0.00	\$4.00	0.00	\$0.00	Replace	Not Given	X SUC
		52462-47130	PAD, RR BUMPER, RH & LH, 3	0.00	\$11.00	0.00	\$0.00	Replace	Not Given	X SUC
		52191-47030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.30	0.00	\$0.00	Replace	Not Given	X SUC
		52575-47060	RETAINER, RR BUMPER, RH	0.00	\$132.60	0.00	\$0.00	Replace	Not Given	X SUC
		52576-47060	RETAINER, RR BUMPER, LH	0.00	\$132.60	0.00	\$0.00	Replace	Not Given	X SUC
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	0.00	\$4.50	0.00	\$0.00	Replace	Not Given	X SUC
		52453-47900	GUARD, RR BUMPER, LOWER	1.00	\$374.50	25.00	\$280.88	Replace	Replace	X CRU
		52169-47070	COVER, GUARD RR BUMPER LOWER	0.00	\$22.00	0.00	\$0.00	Replace	Not Given	X SUC
		52461-47070	PAD, RR BUMPER, CTR	3.00	\$11.00	25.00	\$24.75	Replace	Replace	X NEC
		81910-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, RH	0.00	\$39.00	0.00	\$0.00	Replace	Not Given	X SUC
		81920-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, LH	0.00	\$39.00	0.00	\$0.00	Replace	Not Given	X SUC
		52023-47030	REAR BUMPER REINFORCEMENT	0.00	\$332.70	0.00	\$0.00	Replace	Check	X SUC
		89997-30100	ANTENNA, ELECTRICAL KEY	0.00	\$72.00	0.00	\$0.00	Replace	Check	X SUC

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 08/12/2020

User ID PohSuan

			REVERSE SENSOR, REAR BUMPER	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X	SVC
		58398-47050	COVER, REAR FLOOR UNDER, RH	0.00	\$175.10	0.00	\$0.00	Replace	Not Given	X	SVC
		66259-47010	COVER, REAR FLOOR UNDER CENTER	0.00	\$229.90	0.00	\$0.00	Replace	Not Given	X	SVC
		58399-47030	COVER, REAR FLOOR UNDER, LH	0.00	\$241.90	0.00	\$0.00	Replace	Not Given	X	SVC
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace		NEC
		58307-47100	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$651.00	0.00	\$0.00	Replace	Not Given	X	SVC
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X	SVC
Total					\$3,250.70		\$425.63				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

425.63 ✓
+ 200.00 ✓
+ 260.00 ✓
885.63 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P/P
\$885.63
2 days