



Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705



SMRT Automotive Services Pte Ltd
2 Tanjong Katong Road, Tower 3, Paya
Lebar Quarter, #08-01, Singapore 437161
Tel: 65 69083530 Fax: 65 69083592

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : IV210100075
Date : 06.01.2021
Vehicle No. : SHD6269L
Your Ref No. : TAX/11/20/2057
Our Ref No. : 24108945
Terms : 30 Days

Description	Qty	Unit Cost	Add %	(Discount) Amount	Amount
Parts					
COVER, RR BUMPER ASSY	1.00	\$ 485.60	(100.00)	\$ 485.60	\$ 0.00
PAD, RR BUMPER, RH & LH , 1	0.00	\$ 4.00	0.00	\$ 0.00	\$ 0.00
PAD, RR BUMPER, RH & LH , 2	0.00	\$ 4.00	0.00	\$ 0.00	\$ 0.00
PAD, RR BUMPER, RH & LH , 3	0.00	\$ 11.00	0.00	\$ 0.00	\$ 0.00
SEAL, RR BUMPER ARM, RH & LH	0.00	\$ 11.30	0.00	\$ 0.00	\$ 0.00
RETAINER, RR BUMPER, RH	0.00	\$ 132.60	0.00	\$ 0.00	\$ 0.00
RETAINER, RR BUMPER, LH	0.00	\$ 132.60	0.00	\$ 0.00	\$ 0.00
CLIPS PIECE, FRT & RR BUMPER	0.00	\$ 4.50	0.00	\$ 0.00	\$ 0.00
GUARD, RR BUMPER, LOWER	1.00	\$ 374.50	(25.00)	\$ 93.62	\$ 280.88
COVER, GUARD RR BUMPER LOWER	0.00	\$ 22.00	0.00	\$ 0.00	\$ 0.00
PAD, RR BUMPER, CTR	3.00	\$ 11.00	(25.00)	\$ 8.25	\$ 24.75
REAR BUMPER REFLECTOR ASSY, REFLEX, RH	0.00	\$ 39.00	0.00	\$ 0.00	\$ 0.00
REAR BUMPER REFLECTOR ASSY, REFLEX, LH	0.00	\$ 39.00	0.00	\$ 0.00	\$ 0.00
REAR BUMPER REINFORCEMENT	0.00	\$ 332.70	0.00	\$ 0.00	\$ 0.00
ANTENNA, ELECTRICAL KEY	0.00	\$ 72.00	0.00	\$ 0.00	\$ 0.00
REVERSE SENSOR, REAR BUMPER	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
COVER, REAR FLOOR UNDER , RH	0.00	\$ 175.10	0.00	\$ 0.00	\$ 0.00
COVER, REAR FLOOR UNDER CENTER	0.00	\$ 229.90	0.00	\$ 0.00	\$ 0.00
COVER, REAR FLOOR UNDER , LH	0.00	\$ 241.90	0.00	\$ 0.00	\$ 0.00
PIXEL STICKER	2.00	\$ 60.00	0.00	\$ 0.00	\$ 120.00
END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$ 651.00	0.00	\$ 0.00	\$ 0.00
SEALANT SIKAFLEX	0.00	\$ 37.00	0.00	\$ 0.00	\$ 0.00
Sub-Total					\$ 425.63

Payment Instructions

By Cheque: Crossed and made payable to "SMRT Automotive Services Pte Ltd" with invoice no. indicated on the reverse side. No receipt will be issued unless requested.

By Bank Transfer:

Account Name : SMRT Automotive Services Pte Ltd
Bank Name : DBS Bank Ltd - SGD
Bank Account No.: 018-008617-4
Swift Code : DBSSSGSG

Koo Yew Chung

Koo Yew Chung (Jan 6, 2021 16:01 GMT+8)

Authorised Signature
for SMRT Automotive Services Pte Ltd



Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

SMRT Automotive Services Pte Ltd
2 Tanjong Katong Road, Tower 3, Paya
Lebar Quarter, #08-01, Singapore 437161
Tel: 65 69083530 Fax: 65 69083592

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 1990042802
Invoice No. : IV210100075
Date : 06.01.2021
Vehicle No. : SHD6269L
Your Ref No. : TAX/11/20/2057
Our Ref No. : 24108945
Terms : 30 Days

Description	Qty	Unit Cost	Add %	/ (Discount) Amount	Amount
Labour					
TO REPAIR REAR PORTION	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
Others					
TO RESPRAY REAR BUMPER	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY BUMPER BEAM	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
TO RESPRAY REAR PANEL	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
TO CHECK WIRING AND SYSTEM FUNCTION	1.00	\$ 20.00	0.00	\$ 0.00	\$ 20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	1.00	\$ 20.00	0.00	\$ 0.00	\$ 20.00
TO REMOVE AND REFIT WIRE HARDESS	1.00	\$ 20.00	0.00	\$ 0.00	\$ 20.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	0.00	\$ 120.00	0.00	\$ 0.00	\$ 0.00
TO REPLACE SUNDRY PARTS	0.00	\$ 100.00	0.00	\$ 0.00	\$ 0.00
TO WASH AND VACUUM	0.00	\$ 60.00	0.00	\$ 0.00	\$ 0.00
GRAND TOTAL				\$	885.63

Remark :

Make/Model :
Accident Date : 25.11.2020

Payment Instructions

By Cheque: Crossed and made payable to "SMRT Automotive Services Pte Ltd" with invoice no. indicated on the reverse side. No receipt will be issued unless requested.

By Bank Transfer:

Account Name : SMRT Automotive Services Pte Ltd
Bank Name : DBS Bank Ltd - SGD
Bank Account No.: 018-008617-4
Swift Code : DBSSSGSG

Koo Yew Chung
Koo Yew Chung (Jan 6, 2021 16:01 GMT+8)

Authorized Signature
for SMRT Automotive Services Pte Ltd