

## Section A - Accident Details

|                                    |                                    |
|------------------------------------|------------------------------------|
| Registration Number                | SHB5185L                           |
| Case Reference Number              | TAX/11/20/2055                     |
| Registration Date                  | 1/11/2017                          |
| Company Type                       | SMRT Taxis Pte Ltd                 |
| Make                               | TOYOTA                             |
| Model                              | PRIUS4                             |
| Name of Driver                     | MOHAMED RAMZAN BIN MOHD DALI       |
| Type of Accident                   | Side Swipe                         |
| Accident Date and Time             | 24/11/2020 7:25 PM                 |
| Accident Reported Date and Time    | 25/11/2020 12:57 PM                |
| Is Surveyor Required?              | Yes                                |
| Survey by                          |                                    |
| Vehicle is Towed Back?             | No                                 |
| Towed Back Date and Time           |                                    |
| Replacement Vehicle issued?        | No                                 |
| Job Card Number                    | 24108930                           |
| Special Instruction to ARC, if any | TP / RIGHT PORTION / CHINA TAIPING |
| Prepared Date and Time             | 25/11/2020 4:09 PM                 |
| Chassis Number                     |                                    |
| Mileage                            |                                    |
| Work Shop                          |                                    |
| Repair Completion Date and Time    |                                    |

## Section B - Summary of Repair Estimates

## Summary of Repair Estimates

|                              | Quotation from ARC                                                                  | Adjusted by Surveyor, if applicable                                                 |
|------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Total Labour Cost            | \$676.00                                                                            | \$500.00                                                                            |
| Total Spray Cost             | \$2,412.00                                                                          | \$730.00                                                                            |
| Total Spare Part Cost        | \$9,343.62                                                                          | \$2,827.22                                                                          |
| Total Other Cost             | \$720.00                                                                            | \$200.00                                                                            |
| <b>TOTAL COST</b>            | <b>\$13,151.62</b>                                                                  | <b>\$4,257.22</b>                                                                   |
| <b>Lump Sum Total</b>        | <b>\$13,150.00</b>                                                                  | <b>\$4,250.00 (L/S)</b>                                                             |
| Number of Repair Days        | 6.0                                                                                 | 4.0                                                                                 |
| Prepared / Adjusted By       | Ang Bang Kien                                                                       | Sun Pin (LKK) / China Taiping                                                       |
| ARC / Surveyor Sign Off Date | 01/12/2020 4:45 PM                                                                  | 01/12/2020 10:04 AM                                                                 |
| Signature                    |  |  |
| Remarks                      | Total number of repair days = 4 days.<br>SUP = 0 day.                               | L/S, after paint photo.                                                             |

## Section C - Quotation and Accident Invoice Details

|                  |              |                |  |
|------------------|--------------|----------------|--|
| Quotation Number | QN-2012-0139 | Invoice Number |  |
| Quotation Date   | 14.12.2020   | Invoice Date   |  |
| Invoice Amount   |              | Prepared Date  |  |

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

| Job Scope                  | Quotation from AR | Adjusted by Surveyor, if applicable |
|----------------------------|-------------------|-------------------------------------|
| TO REPAIR FRONT RH PORTION | \$676.00          | \$500.00 ✓                          |
| Total Labour               | \$676.00          | \$500.00                            |

## Part 2 - Spray Painting &amp; Panel Beating Related Works

| Job Scope                            | Quotation from ARC | Adjusted by Surveyor, if applicable |
|--------------------------------------|--------------------|-------------------------------------|
| TO REPSRAY FRONT BUMPER              | \$378.00           | \$200.00 ✓                          |
| TO RESPRAY FRONT BUMPER LOWER GRILLE | \$180.00           | \$0.00                              |
| TO RESPRAY FRONT FENDER RH           | \$378.00           | \$200.00 ✓                          |
| TO RESPRAY APRON PANEL RH            | \$180.00           | \$0.00                              |
| TO RESPRAY RIM                       | \$180.00           | \$50.00 ✓                           |
| TO RESPRAY ROCKER PANEL MOULDING     | \$180.00           | \$0.00                              |
| TO RESPRAY FRONT DOOR RH             | \$378.00           | \$200.00 ✓                          |
| TO RESPRAY REAR DOOR RH              | \$378.00           | \$0.00                              |
| RESPRAY MIRROR COVER RH              | \$180.00           | \$80.00 ✓                           |
| Total Spray Painting & Panel Beating | \$2,412.00         | \$730.00                            |

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

| Job Scope                                       | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------|--------------------|-------------------------------------|
| TO TRANSFER DOOR MECHANISM                      | \$120.00           | \$60.00 ✓                           |
| TO DO WHEEL ALIGNMENT / TYRE BALANCING          | \$120.00           | \$60.00 ✓                           |
| TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE) | \$120.00           | \$30.00 ✓                           |
| TO REMOVE AND REFIX WING MIRROR                 | \$120.00           | \$30.00 ✓                           |
| TO REPLACE SUNDRY PARTS                         | \$100.00           | \$0.00                              |
| TO CHECK WIRING AND SYSTEM FUNCTION             | \$80.00            | \$20.00 ✓                           |
| TO WASH AND VACUUM                              | \$60.00            | \$0.00                              |
| Total Other Costs                               | \$720.00           | \$200.00                            |

## Part 4 - Spare Parts / Material Usage

| Part Number | Portion | Stock Number | Part Name                        | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|-------------|---------|--------------|----------------------------------|----------|-----------------|--------------|------------------|--------------------|-------------------|
|             |         | 8791047450   | MIRROR ASSY, OUTER REAR VIEW, RH | 1.00     | \$1,373.50      | 10.00        | \$1,236.15       | Replace            | Replace ✓ CR4     |
|             |         | 8791547070A1 | COVER, OUTER MIRROR, RH          | 1.00     | \$89.50         | 100.00       | \$0.00           | Replace            | Repair ✓ R        |
|             |         | 5211947962   | COVER, FR BUMPER                 | 1.00     | \$495.50        | 25.00        | \$371.63         | Replace            | Replace ✓ CR4     |
|             |         | 5211547050   | SUPPORT, FR BUMPER RH            | 1.00     | \$76.90         | 25.00        | \$57.68          | Replace            | Replace ✓ BR      |
|             |         | 5211647050   | SUPPORT, FR BUMPER LH            | 0.00     | \$82.30         | 0.00         | \$0.00           | Replace            | Not Given X SUC   |
|             |         | 5311247240   | GRILLE, RADIATOR                 | 0.00     | \$165.00        | 0.00         | \$0.00           | Replace            | Not Given X SUC   |
|             |         | 5310147080   | GRILLE SUB-ASSY                  | 0.00     | \$335.60        | 0.00         | \$0.00           | Replace            | Not Given X SUC   |
|             |         | 5216116010   | CLIPS PIECE, FRT & RR BUMPER     | 0.00     | \$1.50          | 0.00         | \$0.00           | Replace            | Not Given X SUC   |

# SMRT Accident Vehicle Repair Estimates

|                                            |
|--------------------------------------------|
| SMRT Automotive Services Pte Ltd           |
| 60 Woodlands Industrial Park E4, Singapore |
| FAX Number : 6365592                       |
| Estimator Telephone Number : 68662623      |
| Accident Reporting Number : 68662672       |

Date Generated : 14/12/2020

User ID : kimmingchin

|             |                                     |      |             |        |            |         |           |   |     |
|-------------|-------------------------------------|------|-------------|--------|------------|---------|-----------|---|-----|
| 5141047020  | COVER ASSY, ENGINE UNDER CENTER SET | 0.00 | \$452.80    | 0.00   | \$0.00     | Replace | Not Given | X | SVC |
| 5144747030  | COVER, ENGINE UNDER CENTER          | 0.00 | \$94.50     | 0.00   | \$0.00     | Replace | Not Given | X | SVC |
| 8121047020  | LAMP ASSY, FOG, RH                  | 0.00 | \$910.20    | 0.00   | \$0.00     | Replace | Not Given | X | SVC |
| 8114547691  | UNIT, HEADLAMP, RH                  | 0.00 | \$2,558.90  | 0.00   | \$0.00     | Replace | Check     | X | SVC |
| 7537447140  | EMBLEM, SIDE PANEL (HYBRID)         | 1.00 | \$52.90     | 25.00  | \$39.68    | Replace | Replace   |   | NEC |
| 5387547070  | LINER, FR FENDER, RH                | 0.00 | \$198.40    | 0.00   | \$0.00     | Replace | Check     | X | SVC |
| 5385147061  | PAD, FR WHEEL RH                    | 0.00 | \$57.70     | 0.00   | \$0.00     | Replace | Not Given | X | SVC |
| 5380747020  | SEAL SUB-ASSY, RH                   | 0.00 | \$50.20     | 0.00   | \$0.00     | Replace | Check     | X | SVC |
| 5382747050  | PROTECTOR, FR FENDER RH             | 0.00 | \$90.40     | 0.00   | \$0.00     | Replace | Not Given | X | SVC |
| 5370147111  | APRON SUB-ASSY, FRONT FENDER, RH    | 0.00 | \$944.20    | 0.00   | \$0.00     | Replace | Check     | X | SVC |
| 4260247180  | CAP SUB-ASSY, WHEEL                 | 1.00 | \$175.80    | 25.00  | \$131.85   | Replace | Replace   |   | SCR |
| 42611-47450 | WHEEL, DISC FRONT                   | 1.00 | \$1,555.10  | 100.00 | \$0.00     | Replace | Repair    | R | R   |
| 4355047020  | HUB & BEARING ASSY, RH & LH         | 0.00 | \$554.20    | 0.00   | \$0.00     | Replace | Not Given | X | SVC |
|             | TYRE                                | 0.00 | \$126.74    | 0.00   | \$0.00     | Replace | Not Given | X | SVC |
| 7585047910  | MOULDING ASSY, BODY                 | 0.00 | \$576.00    | 0.00   | \$0.00     | Replace | Not Given | X | SVC |
| 6700147152  | ROCKER PANEL, RH                    | 1.00 | \$1,249.60  | 25.00  | \$937.20   | Replace | Replace   |   | CR4 |
|             | PANEL SUB-ASSY, FRONT DOOR RH       | 1.00 | \$60.00     | 0.00   | \$60.00    | Replace | Replace   |   | NEC |
|             | STICKER DECAL SMRT (DOOR)           | 0.00 | \$153.50    | 0.00   | \$0.00     | Replace | Not Given | X | SVC |
| 6861047040  | CHECK ASSY, FRONT DOOR              | 0.00 | \$82.10     | 0.00   | \$0.00     | Replace | Not Given | X | SVC |
| 6871012151  | HINGE ASSY, FRONT DOOR, UPPER RH    | 0.00 | \$92.10     | 0.00   | \$0.00     | Replace | Not Given | X | SVC |
| 6873012120  | HINGE ASSY, FRONT DOOR, LOWER RH    | 0.00 | \$1,243.90  | 0.00   | \$0.00     | Replace | Not Given | X | SVC |
| 6700347210  | PANEL SUB-ASSY, REAR DOOR, RH       | 0.00 | \$83.30     | 0.00   | \$0.00     | Replace | Not Given | X | SVC |
| 6875020122  | HINGE ASSY, REAR DOOR, UPPER RH     | 0.00 | \$73.30     | 0.00   | \$0.00     | Replace | Not Given | X | SVC |
| 6877052031  | HINGE ASSY, REAR DOOR, LOWER RH     | 0.00 | \$153.50    | 0.00   | \$0.00     | Replace | Not Given | X | SVC |
| 6863047050  | CHECK ASSY, REAR DOOR               | 0.00 | \$60.00     | 0.00   | \$0.00     | Replace | Not Given | X | SVC |
|             | PIXEL STICKER                       | 0.00 | \$60.00     | 0.00   | \$0.00     | Replace | Not Given | X | SVC |
| Total       |                                     |      | \$14,269.14 |        | \$2,834.19 |         |           |   |     |

## Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Stock Number | Part Name               | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|-------------|---------|--------------|-------------------------|----------|---------------|--------------|------------------|-----------|----------------|
|             |         | 5380147080   | FENDER SUB-ASSY, FR, RH | 1.00     | \$933.10      | 25.00        | \$699.83         | Replace   | Replace        |
| Total       |         |              |                         |          | 933.10        |              | 699.83           |           |                |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

3534.02 / 20%

2827.22 /

500.00 /

930.00 /

4251.22 /

45 \$4250/-

4 days