



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS3/LPC20001323/Qvd3e2-1	
			Date: 15/12/2020	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 5154B	Veh. Inspected	GBB 9329J	
Policy No.		Coverage (\$)	0.00	
Claim No.	19/20/20/VC00/022944	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	03/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA 150	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JTFAT35Y30K200393	Colour	BLUE	
Odometer	732619 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	BRIDGESTONE	5 mm	
L/H Front Tyre	195 R15	BRIDGESTONE	5 mm	
R/H Rear Tyre	195 R15	BRIDGESTONE	5 mm	
L/H Rear Tyre	195 R15	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/01/2020	Inspection Date	04/02/2020	
Survey held at	ENG SOON PAINTING SVC BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	