

TPA16.
Xiao Chan

DC's AutoMotive Pte Ltd

1 Kaki Bukit Avenue 6, #01-23, Autobay @ Kaki Bukit, Singapore 417883

H/P: 9767 7794 (Donald Chong)

Email: dcautomotive22@gmail.com

JTEGDS2M707087544

Vehicle number: SLS3196G

Vehicle Made & Model: TOYOTA PREVIA

Qty	List Items	Amount \$
1	Front bumper <i>changed</i>	872.90 ✓ <i>705.</i>
1	Front bumper fog lamp - LH <i>changed</i>	381.60 <i>275.</i>
1	Front bumper sponge <i>Not new</i>	182.60 X
1	Front bumper reinforcement <i>new</i>	571.26 X.
2	Front bumper side retainers - L/R @ 89.95 <i>LH and</i>	179.90 <i>89.95</i>
1	Front bumper logo <i>Not new</i>	68.60 X
1	Front fender - LH <i>Not new</i>	811.35 X <i>2142.85</i>
1	Front fender inner shield - LH <i>Not new</i>	289.91 X <i>1607.13</i>
1	Front headlamp - LH <i>changed</i>	2,893.65 <i>905.</i>
1	Front grille <i>Not new</i>	580.95 X
Sub-total		6,832.72
Less 25%		1,708.18
Total List		5,124.54

Special Nett Items

1 set	Front bumper PDC sensor <i>Not new</i>	30	350.00 X
1 set	Front bumper clip <i>new</i>		45.00 - 30
Total Special Nett			395.00

Labour charges

To check front electrical wiring	680	50.00 30.
To respray undercoating		50.00 X.
To respray painting and etc		800.00 250
Panel beating, cut, weld remove & replacing above parts		800.00 300.
Total Labour		1,700.00

L&K Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to change
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 7,219.54

total: 2267.13

L/S: 1.8K

03 Days