



CYCLE & CARRIAGE

AIG-OD (REVERT)
SURVEY: 03/12/20
LKK - STEVE

VEHICLE NO : SMW 676 A

MODEL : KIA/NIRO 1.6 A EX

WIP : 25247

Material	:	\$	<u>1,546.40</u>
Labour	:	\$	<u>3,410.00</u>
Sub-Total	:	\$	<u>4,956.40</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>600.00</u>
Total	:	\$	<u>4,356.40</u>
GST 7%	:	\$	<u>304.95</u>
Grand Total	:	\$	<u>4,661.35</u>
Finalise By/Date : <u>Larry on 17/12/20</u>			



REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING



SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 07 WORKING DAYS + 2 days (wk end)



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 04/12/2020	Cust No/Name	LCV13226/PHAY SU ING, VALERIE (PENG SUYI)
	Reg No/Reg Date	SMW676A / 30/10/2020
	Date In/Mileage	03/12/2020/ 1800
	Chassis/Package	KNACB81CVL5371487 /#
	Engine No	G4LEKS616368
	Make/Model	KIA/NIRO 1.6 A EX A42 PE
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	17/12/2020/ 11:36	BLK	884 / Lauro Songcuan	25247		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							800.00
REPLACE REAR BUMPER & AFFECTED AREAS							
REPAIR ON REAR TAILGATE & REAR LH FENDER							
E PNT98000							1440.00
SPRAY PAINT ON REAR BUMPER, TAILGATE & REAR LH FENDER							
E PNT88000							120.00
REMOVE & INSTALL REAR PARKING ASSIST							
M SUNDRY							40.00
PERFORM RUST PREVENTION ON AFFECTED PORTIONS							
A 54900099							30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
M SUNDRY							40.00
SUPPLY C&C EMBLEM							
M SUNDRY							20.00
SUNDRIES							
S SPECIALISTJOB							50.00
SUPPLY REAR NUMBER PLATE WITH FRAME							
E PNT88000							400.00
REPAIR END PANEL → <i>Supp</i>							
E PNT98000							350.00
SPRAY PAINT END PANEL → <i>Supp</i>							
X EXC							-600.00
INSURANCE EXCESS							
X COVER-RR BUMPER,UPR ✓				1.00	486.00	20.00	388.80
X COVER-RR BUMPER LWR ✓				1.00	392.00	20.00	313.60
X SKID PLATE-RR BUMPER ✓				1.00	98.00	20.00	78.40
X COVER-RR BUMPER SIDE UNDER,LH ✓				1.00	12.00	20.00	9.60
X COVER- RR REFLECTOR, LH ✓				1.00	51.00	20.00	40.80
X LAMP ASSY-REAR FOG & R/REFL,LH ✓				1.00	364.00	20.00	291.20
X BEAM-RR BUMPER ?				1.00	261.00	20.00	208.80

This is not an official tax invoice.
This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 04/12/2020	<table> <tr> <td>Cust No/Name</td><td>LCV13226/PHAY SU ING, VALERIE (PENG SUYI)</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMW676A / 30/10/2020</td></tr> <tr> <td>Date In/Mileage</td><td>03/12/2020/ 1800</td></tr> <tr> <td>Chassis/Package</td><td>KNACB81CVL5371487 /#</td></tr> <tr> <td>Engine No</td><td>G4LEKS616368</td></tr> <tr> <td>Make/Model</td><td>KIA/NIRO 1.6 A EX A42 PE</td></tr> <tr> <td>Colour/Trim</td><td>CR5 RUNWAY RED / WK SATURN BLACK</td></tr> </table>	Cust No/Name	LCV13226/PHAY SU ING, VALERIE (PENG SUYI)	Reg No/Reg Date	SMW676A / 30/10/2020	Date In/Mileage	03/12/2020/ 1800	Chassis/Package	KNACB81CVL5371487 /#	Engine No	G4LEKS616368	Make/Model	KIA/NIRO 1.6 A EX A42 PE	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK
Cust No/Name	LCV13226/PHAY SU ING, VALERIE (PENG SUYI)														
Reg No/Reg Date	SMW676A / 30/10/2020														
Date In/Mileage	03/12/2020/ 1800														
Chassis/Package	KNACB81CVL5371487 /#														
Engine No	G4LEKS616368														
Make/Model	KIA/NIRO 1.6 A EX A42 PE														
Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	17/12/2020/ 11:36	BLK	884 / Lauro Songcuan	25247

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X STAY-RR BUMPER LH ?	1.00	67.00	20.00	53.60 ?
X STAY-RR BUMPER RH ?	1.00	67.00	20.00	53.60 ?
X BRACKET ASSY-RR BUMPER SIDE, LH ✓	1.00	25.00	20.00	20.00 ✓
X EMBLEM-NIRO ✓	1.00	25.00	20.00	20.00 ✓
X LOGO-KIA ✓	1.00	42.00	20.00	33.60 ✓
X EMBLEM-ECO HYBRID ✓	1.00	29.00	20.00	23.20 ✓
X CLIP	10.00	1.00	20.00	8.00 x
X NUT-PLUG	2.00	2.00	20.00	3.20 x

Z TEXT
 AIG OD CLAIM - REVERT
 DOA: 02.12.2020
 SURVEY: STEVE (LKK) 03/12/2020
 07 DAYS

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	1,546.40	Nett	4,356.40
Labour	3,260.00	7% GST on	304.95
Standard Menu	0.00		
Specialist Job	50.00		
Diagnostics Job	0.00		
Sundry/Others	-500.00		
Total(w/o GST)	4,356.40	Total Payable	4,661.35

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMW 676 A

Materials

- 1 Clip (10 pcs)
- 2 Nut- Plug (2 pcs)

Cost \$

10.00 / NEC

4.00 / NEC

14.00

20% Discount

2.80

11.20

Labour

- 1 Repair End panel
- 2 Spray Paint End Panel

400.00 /

350.00 /

750.00

Labour & Materials

761.20

7% GST

53.28

Total

814.48

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SNW 676 AWIP: 25247

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Beam Rear Bumper	? / SUPP			86631 65500
2	Steering LH	? / SUPP			86641 65500
3	Steering RH	? / SUPP			86642 65500
4	Clips 100 pcs	? / SUPP			1420608 25008 10yr
5	Nut 100 pcs	? / SUPP			84145 26000
6	Repair End panel	? / SUPP			
7	Painting in End panel	? / SUPP			
8	3x18 1/2 Special Red CES	? / SUPP			
9	Add 02 day - Total 07 day	? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	7/12/20	Steve
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Niro 1.6 EXSURVEYOR: Ukk Steve

HOME
 Online

Niro(DE HEV)/2020/G 1.6 GDI..

VCI

Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save

VESS
 IGPM
 BCM
 IBU-TP

18/18

System	Status	Result
ENGINE	No Current DTC	Good
MCU	No Current DTC	Good
HCULDC	No Current DTC	Good
BMS	No Current DTC	Good
AT	No Current DTC	Good
ESCAHB	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0234	VCI Ver.	02.48
ECU Ver.	M-E-K-01-00-0175	OS Ver.	Android 9

HOME
 Online

Niro(DE HEV)/2020/G 1.6 GDI..

VCI

Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save

VESS
 IGPM
 BCM
 IBU-TP

18/18

System	Status	Result
ENGINE	No Current DTC	Good
MCU	No Current DTC	Good
HCULDC	No Current DTC	Good
BMS	No Current DTC	Good
AT	No Current DTC	Good
ESCAHB	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0234	VCI Ver.	02.48
ECU Ver.	M-E-K-01-00-0175	OS Ver.	Android 9