



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV13226/PHAY SU ING, VALERIE (PENG SUYI)
	Reg No/Reg Date	SMW676A / 30/10/202
	Date In/Mileage	03/12/2020/ 0
	Chassis No	KNACB81CVL5371487
	Engine No	G4LEKS616368
	Make/Model	KIA/NIRO 1.6 A EX A42 PE
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	03/12/2020/ 16:13	QUK	282 / Kevin Leong	25247			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR BUMPER, END PANEL & AFFECTED AREA 4'0								809 2000.00
REPAIR ON REAR TAILGATE & REAR LH FENDER								1449 1920.00
E PNT98000 PAINT WORK ON REAR BUMPER, TAILGATE, END PANEL & REAR LH FENDER 480 x 4								120.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST								? 120.00
E PNT88000 REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR								? 40.00
M SUNDRY TO APPLY SEALANT ON AFFECTED AREA								40.00
M SUNDRY PERFORM RUST PREVENTION								30.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								40.00
M SUNDRY TO SUPPLY C & C EMBLEM								50.00
M SUNDRY TO SUPPLY REAR NUMBER PLATE WITH FRAME								20 50.00
M SUNDRY SUNDRIES								
M PANEL ASSY-BACK ? X R					1.00	526.00	20.00	420.80
M COVER-RR BUMPER,UPR / CRU					1.00	486.00	20.00	388.80
M COVER-RR BUMPER LWR / BR					1.00	392.00	20.00	313.60
M SKID PLATE-RR BUMPER / CRU					1.00	98.00	20.00	78.40
M COVER-RR BUMPER SIDE UNDER,LH / BR					1.00	12.00	20.00	9.60
M MOULDING ASSY-RR BUMPER SIDE,L ? X N/N					1.00	15.00	20.00	12.00
M MOULDING ASSY-RR BUMPER SIDE,R ? X N/N					1.00	15.00	20.00	12.00
M COVER- RR REFLECTOR, LH / CUT					1.00	51.00	20.00	40.80
M LAMP ASSY-REAR FOG & R/REFL,LH / CUT					1.00	364.00	20.00	291.20

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV13226/PHAY SU ING, VALERIE (PENG SUYI) Reg No/Reg Date SMW676A / 30/10/202 Date In/Mileage 03/12/2020/ 0 Chassis No KNACB81CVL5371487 Engine No G4LEKS616368 Make/Model KIA/NIRO 1.6 A EX A42 PE Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	03/12/2020/ 16:13	QUK	282 / Kevin Leong	25247			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	COVER-RR BUMPER SIDE UNDER,RH	X	NN		1.00	12.00	20.00	9.60
M	BRACKET-RR BEAM UPR MTG,LH	X	NN		1.00	5.00	20.00	4.00
M	BRACKET-RR BEAM LWR MTG,LH	X	NN		2.00	5.00	20.00	8.00
M	BRACKET-RR BEAM UPR MTG,RH	X	NN		1.00	5.00	20.00	4.00
M	BEAM-RR BUMPER				1.00	261.00	20.00	208.80
M	STAY-RR BUMPER LH				1.00	67.00	20.00	53.60
M	STAY-RR BUMPER RH				1.00	67.00	20.00	53.60
M	BRACKET ASSY-RR BUMPER SIDE,LH				1.00	25.00	20.00	20.00
M	BRACKET ASSY-RR BUMPER SIDE,RH				1.00	25.00	20.00	20.00
M	EMBLEM-NIRO				1.00	25.00	20.00	20.00
M	LOGO-KIA				1.00	42.00	20.00	33.60
M	EMBLEM-ECO HYBRID				1.00	29.00	20.00	23.20

Estimate

Steve (LKK) 3/12/20, 4.30pm
 OD - Not Authral
 EXCESS - ?
 P/P
 By Bel spy
 7 days

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature:
 Date:

	Nett	6,555.60
7% GST on	6555.60	458.89
Total Payable		7,014.49

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.