

ASS. REC. BY: SteveREF: AIG

CS/AIG20013349/Eqf3

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____


Insured: _____

Policy No. 2070153500Claims No. 9361861635SGSum Insured: _____ Excess: 600

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 85K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMW 676AYr Regn: 30/10/20Type ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: KIA Niroc.c 1580Colour: RedA/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NSp. Reading: 1800T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ N

Eng/No: _____

C/No: KNACB81CVLSJ71487Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim orTyre Size: F: 205/60R16R: 11BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 5 mmR/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mmD.O.A. 2/12/20D.O.I. 3/12/20Survey held at Cycle N CarriageDes. of Damages: Frt ☒ Rear ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MK-

04/12/20 @ 2.39pm revert to AIG via Merimen.

04/12/20 @ 4.51pm Kok Chong informed C/A via Merimen.

04/12/20 @ 5.06pm Informed Kevin C/A & ex: \$600 by email.

Date/Time, File, Pass to?



: Prell. Report



: Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$



: Interview (\$



: Tech. Inve (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Pop. Form:

Lump Sum / L.E.:

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name: LCV13226/PHAY SU ING, VALERIE (PENG SUYI) Reg No/Reg Date: SMW676A / 30/10/202 Date In/Mileage: 03/12/2020/ 0 Chassis No: KNACB81CVL5371487 Engine No: G4LEKS616368 Make/Model: KIA/NIRO 1.6 A EX A42 PE Colour/Trim: CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	03/12/2020/ 16:13	QUK	282 / Kevin Leong	25247

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR BUMPER, END PANEL & AFFECTED AREA 4'0				809 2000.00
REPAIR ON REAR TAILGATE & REAR LH FENDER				1447 1920.00
E PNT98000 PAINT WORK ON REAR BUMPER, TAILGATE, END PANEL & REAR LH FENDER 480 x 4				120.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST				120.00
E PNT88000 REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR				40.00
M SUNDRY TO APPLY SEALANT ON AFFECTED AREA				40.00
M SUNDRY PERFORM RUST PREVENTION				30.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				40.00
M SUNDRY TO SUPPLY C & C EMBLEM				50.00
M SUNDRY TO SUPPLY REAR NUMBER PLATE WITH FRAME				20 50.00
M SUNDRY SUNDRIES				
M PANEL ASSY-BACK	1.00	526.00	20.00	420.80
M COVER-RR BUMPER,UPR / CRU	1.00	486.00	20.00	388.80
M COVER-RR BUMPER LWR / BR	1.00	392.00	20.00	313.60
M SKID PLATE-RR BUMPER / CRU	1.00	98.00	20.00	78.40
M COVER-RR BUMPER SIDE UNDER,LH / BR	1.00	12.00	20.00	9.60
M MOULDING ASSY-RR BUMPER SIDE,L / ?	1.00	15.00	20.00	12.00
M MOULDING ASSY-RR BUMPER SIDE,R / ?	1.00	15.00	20.00	12.00
M COVER- RR REFLECTOR, LH / CUT	1.00	51.00	20.00	40.80
M LAMP ASSY-REAR FOG & R/REFL,LH / CUT	1.00	364.00	20.00	291.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address

AIG Asia Pacific Insurance Pte.
Ltd.
MOTOR CLAIM DEPARTMENT
78 SHENTON WAY #08-16
AIG BUILDING
SINGAPORE 079120
Contact No 64191000

Owner Name & Vehicle Info

Cust No/Name LCV13226/PHAY SU ING, VALERIE (PENG SUYI)
Reg No/Reg Date SMW676A / 30/10/202
Date In/Mileage 03/12/2020/ 0
Chassis No KNACB81CVL5371487
Engine No G4LEK5616368
Make/Model KIA/NIRO 1.6 A EX A42 PE
Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	03/12/2020/ 16:13	QUK	282 / Kevin Leong	25247

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M COVER-RR BUMPER SIDE UNDER, RH X	1.00	12.00	20.00	9.60
M BRACKET-RR BEAM UPR MTG, LH	1.00	5.00	20.00	4.00
M BRACKET-RR BEAM LWR MTG, LH	2.00	5.00	20.00	8.00
M BRACKET-RR BEAM UPR MTG, RH	1.00	5.00	20.00	4.00
M BEAM-RR BUMPER	1.00	261.00	20.00	208.80
M STAY-RR BUMPER LH	1.00	67.00	20.00	53.60
M STAY-RR BUMPER RH	1.00	67.00	20.00	53.60
M BRACKET ASSY-RR BUMPER SIDE, LH	1.00	25.00	20.00	20.00
M BRACKET ASSY-RR BUMPER SIDE, RH	1.00	25.00	20.00	20.00
M EMBLEM-NIRO	1.00	25.00	20.00	20.00
M LOGO-KIA	1.00	42.00	20.00	33.60
M EMBLEM-ECO HYBRID	1.00	29.00	20.00	23.20

Estimate

ster (LKK) 3/12/20, 4.30pm
 OD - Not Auth
 EXCESS - ?
 P/P
 Ry Bel spy
 5 days

KK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

7% GST on Net 6,555.60 458.89
 Total Payable 7,014.49

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.