



ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0940/2020/NS
DATE	:	2-Dec-20
WIP	:	60836

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT**TEL: 6841 0055 - FAX: 6256 4315**

OWNER'S NAME	:	MDM GUO YA-WEN
ADDRESS	:	BLK 673A JURONG WEST STREET 65 #10-28 SINGAPORE 641673
TELEPHONE	:	HP +65 90930988
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2070138029
VEHICLE NO	:	SMU 1088 B
MODEL CODE	:	AUDI A6 DESIGN 2.0 TFSI S
MODEL YEAR	:	24/9/2020
ENGINE NO	:	DKY 013858
CHASSIS NO	:	WAUZZZF26LN056216
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	2-Nov-20
PLACE OF ACCIDENT	:	IMM CARPARK



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 1088 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00 ✓	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00 500	
3	TO RESPRAY REAR BUMPER.	\$ 1,000.00 550	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 2,752.00</u>	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 1088 B

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	REMARKS
S/NETT			
1 REAR BUMPER <i>Del d</i>	\$	2,639.00 ✓	
2 REAR BUMPER FIXING PARTS <i>Neu</i>	\$	234.00 ✓	X
3 REAR BUMPER SPOILER <i>let</i>	\$	875.00 ✓	
4 REAR BUMPER TRIM - RH <i>Neu</i>	\$	242.00 ✓	
5 REAR BUMPER TRIM - CENTRE <i>Neu</i>	\$	171.00 ✓	
6 REAR BUMPER SECURING STRIP ?	\$	170.00 ?	
7 TELEPHONE AERIAL <i>Neu</i>	\$	178.00 ✓	
8 REAR LIGHT REFLECTOR - RH OUTER ?	\$	41.00 ?	
9 REAR LIGHT REFLECTOR - RH INNER <i>Neu</i>	\$	30.00 ✓	
10 REAR BUMPER CARRIER <i>Neu</i>	\$	915.00 ✓	
11 REAR BUMPER CARRIER SEAL - LH/RH <i>Neu 2</i>	\$	28.00 ✓	
12 REAR BUMPER GUIDE SECTION - RH LOWER } <i>Neu</i>	\$	63.00 ✓	
13 REAR BUMPER GUIDE SECTION - RH UPPER } <i>Neu</i>	\$	45.00 ✓	
14 REAR BUMPER HOLDING STRAP - CENTRE } <i>Neu</i>	\$	116.00 ✓	
15 REAR BUMPER GUIDE PROFILE - RH } <i>Neu</i>	\$	66.00 ✓	
16 REAR PARKING AID SENSOR ?	\$	242.00 ?	
17 REAR PARKING AID SEAL RING ?	4 \$	14.00 ?	
18 SUNDRIES ?	\$	200.00 ?	
TOTAL SPARE PARTS	:	\$ 6,269.00	
TOTAL LABOUR CHARGES	:	\$ 2,752.00	
GRAND TOTAL	:	\$ 9,021.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *04/12/20*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT