

REVERSE CAMERA ASSY <i>Mal</i>	SN	1	\$380.00	\$380.00	X
REAR TRUNK LOWER W/S MOULDING <i>Hec</i>	SN	1	\$180.00	\$180.00	✓
REAR LOWER W/S SEALANT <i>Hec</i>	SN	1	\$46.00	\$46.00	✓
REAR WINDSCREEN MOULDING <i>Hec</i>	SN	1	\$160.00	\$160.00	X
REAR WINDSCREEN SEALANT <i>Hec Hec</i>	SN	1	\$46.00	\$46.00	✓
REAR NO. PLATE WITH COVER <i>st</i>	SN	1	\$45.00	\$45.00	✓
REAR TRUNK LID APPS STICKER <i>Hec</i>	SN	1	\$40.00	\$40.00	✓
REAR TRUNK LID COMFORT & TEL NO. STICKER <i>Hec</i>	SN	1	\$60.00	\$60.00	✓
REAR BUMPER REVERSE SENSOR <i>Don</i>	SN	1	\$135.70	\$135.70	✓
REAR BUMPER RUBBER MAT <i>defunct</i>	SN	1	\$50.00	\$50.00	✓
REAR FENDER ADVERTISEMENT LOGO (LH/RH) <i>Hec</i>	SN	2	\$100.00	\$200.00	✓
REAR DOOR COMFORT & APPS STICKER (LH/RH) <i>Hec</i>	SN	2	\$80.00	\$160.00	✓
REAR DOOR ADVERTISEMENT LOGO (LH/RH) <i>Hec</i>	SN	2	\$100.00	\$200.00	✓
SUB TOTAL			<i>1162.70</i>	\$1,702.70	
Labour Charge					
Panel Beating		1	\$1,800.00	\$1,800.00	1500/-
Spray Painting Charge		1	\$1,600.00	\$1,600.00	1400/-
Wiring Charge		1	\$180.00	\$180.00	30/-
Tuff Kote		1	\$160.00	\$160.00	40/-
Towing Charge		1	\$80.00	\$80.00	Hec
Remove/Refix Cushion & Upholstery Rear		1	\$150.00	\$150.00	80/-
Remove/Refix Rear Windscreen Glass		1	\$120.00	\$120.00	80/-
Remove/Refix Reverse Sensor <i>3230.00</i>		1	\$120.00	\$120.00	40/-
Remove/Refix Exhaust Pipe		1	\$80.00	\$80.00	60/-
Transfer of Door Mechanism REAR		1	\$80.00	\$80.00	Hec
Re-set Rear Power Window System		1	\$200.00	\$200.00	Hec
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$550.00	Hec
TOTAL LABOUR				\$5,120.00	
ESTIMATE TOTAL				\$42,936.22	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

04/12/2020 @ 1700hrs

Not Author

2/Some 21 days.

Yes

LKK Auto

[Signature]

23706.10

SWP 4946.62

28652.72

45 22,900/-

Provide Book Value before finalization.

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIFROST AUTO PTE LTD

REPAIR SUPPLEMENTARY

DATE: 10-Dec-20

INSURANCE: III

MODEL: TOYOTA PRIUS

VEHICLE NO.: SH 6983 G (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR SEAT LOWER CUSHION <i>st (damaged) 50% dep</i>	1	\$3,110.00	\$3,110.00
FRONT CUSHION SEAT <i>st 50% dep</i>	1	\$1,180.00	\$1,180.00
ROOF PANEL <i>rep</i>	1	\$3,120.00	\$3,120.00
REAR DOOR SAFETY BELT (LH/RH) <i>revised</i>	2	\$838.00	\$1,676.00
ROOF LINING <i>clumped/st</i>	1	\$2,059.50	\$2,059.50
SUB TOTAL			\$11,145.50
LESS 20% <i>25%</i>			\$2,229.10
DISCOUNTED TOTAL			\$8,916.40

1555.00
 ✓ SH
 ✓ 590.00
 X SH
 ✓
 ✓

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Man

2kk Auto

List SH
 3735.50 2145.00
 25% 2801.62

8

4946.62