

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

TP III
Jasper.

Contact : 66550005-GRAB 97905299

ESTIMATE

Repair Code : CLM16575
Date in : 03/12/2020
Vehicle Num. : SLX4127Z
Model : HONDA VEZEL HYBRID 1.5X BRILLIANT STYLE AUTO
Chassis/Eng# : RU31262564/LEB5962579

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>distal</i>	1	762.70	✓ 762.70
REAR BUMPER LOWER COVER <i>could</i>	1	250.00	✓ 250.00
REAR BUMPER RH REFLECTOR <i>could</i>	1	141.10	✓ 141.10
REAR BUMPER RH SIDE <i>could</i>	1	195.00	✓ 195.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	23.00	✓ 46.00
REAR END PANEL <i>2x</i>	1	415.60	✗ 415.60
REAR END PANEL INNER TOP GARNISH <i>could</i>	1	98.00	✓ 98.00
REAR EXHAUST CHROME TAIL PIPE <i>2</i>	1	135.00	✗ 135.00
REAR EXHAUST RUBBER MOUNTING <i>new</i>	2	16.50	✗ 33.00
REAR EXHAUST SILENCER BOX	1	517.70	✗ 517.70
REAR EXHAUST SILENCER BOX GASKET <i>new</i>	1	48.30	✗ 48.30
REAR FLOOR PANEL COMPARTMENT TRAY GARNISH <i>could</i>	1	485.30	264 ✗ 485.30
REAR RH FENDER ARCH GARNISH <i>new</i>	1	195.00	✗ 195.00
REAR RH FENDER INNER TRIM GARNISH <i>could</i>	1	295.00	✓ 295.00
REAR RH TAILLAMP <i>could</i>	1	474.60	✓ 474.60
REAR TAILGATE <i>distal</i>	1	953.30	✓ 953.30
REAR TAILGATE 'HYBRID' EMBLEM <i>2x</i>	1	75.80	✓ 75.80
REAR TAILGATE 'VEZEL' EMBLEM	1	56.20	✓ 56.20

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 97905299

ESTIMATE

Repair Code : CLM16575

Date in : 03/12/2020

Vehicle Num. : SLX4127Z

Model : HONDA VEZEL HYBRID 1.5X BRILLIANT STYLE AUTO

Chassis/Eng# : RU31262564/LEB5962579

REAR TAILGATE INNER PULL GARNISH <i>new</i>	1	27.50	<i>x</i>	27.50
REAR TAILGATE INNER TRIM GARNISH <i>cutted</i>	1	153.40	<i>✓</i>	153.40
REAR TAILGATE MECHANISM LOCK <i>Damaged</i>	1	180.00	<i>✓</i>	180.00
REAR TAILGATE RUBBER GUIDE STOPPER L/R <i>new</i>	2	18.50	<i>x</i>	37.00
REAR TAILGATE WEATHER STRIP <i>Not in</i>	1	96.80	<i>x</i>	96.80
REAR TAILGATE WINDSCREEN INNER SEAL <i>3 new</i>	2	50.00	<i>80 ✓</i>	100.00
REAR TAILGATE WINDSCREEN MOULDING	2	50.00	<i>80 ✓</i>	100.00
Subtotal before discount				5,872.30
Percentage discount 20%				1,174.46
Sub-total 1				4,697.84
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	<i>30 ✓</i>	50.00
REAR BUMPER REVERSE SENSOR <i>Damaged</i>	1	250.00	<i>200 ✓</i>	250.00
REAR RH FENDER ARCH GARNISH CLIPS - SET <i>new</i>	1	30.00	<i>20 ✓</i>	30.00
REAR RH FENDER INNER TRIM GARNISH CLIPS - SET <i>new</i>	1	30.00	<i>✓</i>	30.00
REAR RH TAILLAMP CLIPS - SET <i>new</i>	1	30.00	<i>20 ✓</i>	30.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET <i>new</i>	1	100.00	<i>30 ✓</i>	100.00
REAR TAILGATE OUTER GARNISH CLIPS - SET <i>new</i>	1	40.00	<i>300 x</i>	40.00
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1	60.00	<i>✓</i>	60.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 97905299

ESTIMATE

Repair Code : CLM16575

Date in : 03/12/2020

Vehicle Num. : SLX4127Z

Model : HONDA VEZEL HYBRID 1.5X BRILLIANT STYLE AUTO

Chassis/Eng# : RU31262564/LEB5962579

Subtotal before discount	590.00
Percentage discount 0%	0.00
Sub-total 2	590.00
Parts-total	5,287.84

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

60.00
120 150.00
60 120.00
800 1,200.00
80 120.00
800 1,100.00
60 80.00
80.00

Labour Total

2,910.00

Parts & Labour Total

8,197.84

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

*** This is a computer-generated document which requires no signature. ***

page 3

Adrian Lj
L/S 07/12/20

06 Days.

Total: 5737.08

L/S: A.SK ✓