

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	BLUWEL AUTOMO	TIVE SERVICE PTE LTD		Ref:	CS/TP20013370/Utf3e2	
	BLK 1 KAKI BUKIT #01-28/51/53/55(M 417883	AVE 6 AIN OFFICE)SINGAPORE		Date:	29/12/2020	
	ON BEHALF OF D	YLAN ZHANG YINGJIE		Code:	TP149	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.		Veh. Inspected		SLS 8153Y	
	Policy No.		Coverage (\$)		0.00	
	Claim No.		Excess (\$)		0.00	
	Assign From		Assign Date		04/12/2020	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA C-HR HYBRID (A)	c.c		1797	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	ZYX102068434	Colour		YELLOW	
	Odometer	38777 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/50 R18	BRIDGESTONE		7 mm	
	L/H Front Tyre	225/50 R18	BRIDGESTONE		7 mm	
	R/H Rear Tyre	225/50 R18	BRIDGESTONE		7 mm	
	L/H Rear Tyre	225/50 R18	BRIDGESTONE		7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	03/12/2020	Inspection Dat	е	04/12/2020	
	Survey held at BLUWEL AUTOMOTIVE SERVICE PTE LTD					
		BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				