

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 8 December 2020 10:55 AM
To: Don Bong Kiong Hua
Cc: Coco Lu Ting; Edwin Abcede Caina; Kevin Leong Wai Kit; Andre Chow En De; SUR
Subject: RE: SMK3117R / OD / AIG

Dear Don,

Please be informed that the excess of SMK 3117R should be \$300.00 instead of \$600.00.

"Best Wishes for Merry Christmas & Happy New Year 2021"

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Monday, 7 December 2020 12:10 PM
To: Don Bong Kiong Hua <kionghua.bong@cyclecarriage.com.sg>
Cc: Coco Lu Ting <coco.lu@cyclecarriage.com.sg>; Edwin Abcede Caina <edwin.caina@cyclecarriage.com.sg>; Kevin Leong Wai Kit <kevin.leong@cyclecarriage.com.sg>; Andre Chow En De <andre.chow@cyclecarriage.com.sg>; SUR <sur@lkkauto.com>
Subject: SMK3117R / OD / AIG

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SMK 3117R (Excess \$600/-)**.

Before paint photos for Front Bumper and New Part required after repair

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)