

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : GOH EE PING
38 JALAN BANGAU

SINGAPORE 809382

ATTN:

Your Ref No: SKK4796Y
Claim Type: Third Party → Acc
Accident Date: 01/12/2020
TP Veh Reg No: SMS8453U

Estimate No: MC1901586
Date: 04 Dec 2020
Policy No: P10208205R01
Veh Reg No: SKK4796Y
Make/Model: VOLKSWAGEN JETTA
1.4 TSI AT

Not Authorised
Repair by paint 3 days

Estimate Repair Cost to Vehicle No :SKK4796Y

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 SIDE MIRROR ARM RH	1 PC	390.05	?
2 SIDE MIRROR COVER RH	1 PC	197.25	X
3 SIDE MIRROR GLASS RH	1 PC	193.60	✓
4 SIDE MIRROR SIGNAL LAMP RH	1 PC	102.30	X
5 FRONT DOOR RH	1 PC	1,963.45	X
6 FRONT DOOR RUBBER (AT DOOR)	1 PC	114.30	X
		2,960.95	
	Less 10%	296.10	2,664.86
LABOUR			
7 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.	1 PC	60.00	4d
8 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD . TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	400.00	200d
9 TO SPRAY FRONT DOOR RH, SIDE MIRROR RH.	1 PC	400.00	250d
		860.00	860.00
Total			SS 3,524.86
Add GST @ 7%			246.74
Total Amount Payable			SS 3,771.60

TOTAL: SINGAPORE DOLLAR THREE THOUSAND SEVEN HUNDRED SEVENTY ONE AND CENTS SIXTY ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE