



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV12109/NG WEI LING, ROSALYN (HUANG WEI Reg No/Reg Date SMP2720D / 19/09/201 Date In/Mileage / 15646 Chassis No MMBSTA13AKH003367 Engine No 3A92UJB1447 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim PO1 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	04/12/2020/ 16:06	QUD	247 / DonBong	60385			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, FRONT BODY KITS, RH FRONT FENDER, LH FRONT FENDER					1			2250.00
E PNT88000 REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK								100.00
A 55900099 TOP UP AIR CON GAS AND CHECK A/CON SYSTEM								80.00
E PNT98000 PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, FRONT BODY KITS, RH FRONT FENDER, LH FRONT FENDER AND AFFECTED PORTION					1			2450.00
M SUNDRY APPLY BODY SEALANT								160.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								30.00
M SUNDRY PERFORM RUST PREVENTION								120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY SUPPLY FRONT NUMBER PLATE WITH FRAME								50.00
M SUNDRY SUNDRIES								50.00
M PANEL, HEADLAMP SUPPORT, UPR					1.00	65.00	23.00	50.05
M PANEL ASSY, FR END					1.00	1055.00	23.00	812.35
M CONDENSER ASSY, A/C REFRIGE					1.00	758.00	23.00	583.66
M PANEL, AIR GUIDE					1.00	112.00	23.00	86.24
M RADIATOR ASSY					1.00	967.00	23.00	744.59
M FAN, COOLING, LH					1.00	77.00	23.00	59.29
M SHROUD, COOLING FAN					1.00	130.00	23.00	100.10

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV12109/NG WEI LING, ROSALYN (HUANG WEI) Reg No/Reg Date SMP2720D / 19/09/201 Date In/Mileage / 15646 Chassis No MMBSTA13AKH003367 Engine No 3A92UJB1447 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim PO1 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
KAX00008	Credit	04/12/2020/ 16:06	QUD	247 / DonBong	60385				
Description of Goods / Services									
M MOTOR, COOLING FAN						1.00	479.00	23.00	368.83
M TANK ASSY, RADIATOR COND						1.00	42.00	23.00	32.34
M LLC 4L						1.00	26.00	23.00	20.02
M PANEL, AIR GUIDE, RH						1.00	11.00	23.00	8.47
M PANEL, AIR GUIDE, LH						1.00	11.00	23.00	8.47
M HEADLAMP ASSY, LH						1.00	660.00	23.00	508.20
M HEADLAMP ASSY, RH						1.00	660.00	23.00	508.20
M GRILLE, RADIATOR						1.00	554.00	23.00	426.58
M MARK, THREE-DIA						1.00	69.00	23.00	53.13
M BRACKET, FR BUMPER, LH						1.00	13.00	23.00	10.01
M BRACKET, FR BUMPER, RH						1.00	13.00	23.00	10.01
M GRILLE, FR UNDER						1.00	165.00	23.00	127.05
M GARNISH, FR BUMPER, LH						1.00	127.00	23.00	97.79
M GARNISH, FR BUMPER, RH						1.00	127.00	23.00	97.79
M COVER, HEADLAMP SUPT PANEL						1.00	62.00	23.00	47.74
M CLIP, FR BUMPER						10.00	4.00	23.00	30.80
M FACE, FR BUMPER						1.00	703.00	23.00	541.31
M BODY KIT, ATTRAGE						1.00	1643.00	00.00	1643.00
M LATCH, HOOD						1.00	69.00	23.00	53.13
M CLIP, HOOD INSULATOR						1.00	3.00	23.00	13.86
M INSULATOR, HOOD						6.00	177.00	23.00	136.29
M HINGE, HOOD, RH						1.00	56.00	23.00	43.12
M HINGE, HOOD, LH						1.00	56.00	23.00	43.12
M HOOD						1.00	734.00	23.00	565.18
M FENDER, FR LH						1.00	497.00	23.00	382.69
M FENDER, FR RH						1.00	497.00	23.00	382.69
M EMBLEM ECO						1.00	17.00	00.00	34.00
M LH GARNISH, FR FENDER						2.00	65.00	23.00	50.05
M RH GARNISH, FR FENDER						1.00	65.00	23.00	50.05

SURVEYOR NAME: Steve CLKK

SURVEYOR SIGNATURE: [Signature]

DATE: 8 days

REMARKS: PIP

7% GST on

Nett 14,140.20

14,140.20
989.81

Total Payable

15,130.01

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Third party Authorised - [Signature] company stamp

No illegal modifications is allowed. Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Supplementary costs quoted are excluded. GST. We would mention that the above estimate is based on our initial inspection and does not include parts that may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing.