

4th MSIA 2019

Not Authorized
dhr

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

4/5 \$4000
4 days 4/12/20

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3011/12/20

Your Ref:

Date: 5th DEC 2020

MR TAN HOCK GUAN
BLK 19, HOUGANG AVENUE 3,
#04-201, SINGAPORE 530019

Wong Hock Guan

Estimate cost of repair to TOYOTA COROLLA ALTIS 1.6 (A) Saloon - SKW 8906 H

1 pc front o/s door	30d/ydd		\$ 1,079.60	✓
1 set front o/s door frame sticker	nu		79.20	✓
1 pc front o/s door glass regulator	11		228.60	X
1 pc front o/s door glass outer moulding	nu		150.30	✓
1 pc front o/s door weatherstrip	nu		157.80	✓
1 pc front o/s door inner lock	11		577.10	X
16 pcs front o/s door trim board clips	11	@ \$ 4.80	76.80	X
1 pc rear o/s door	30d/ydd		1,069.20	✓
1 set rear o/s door frame sticker	nu		74.30	✓
1 pc rear o/s door glass regulator	11		212.40	X
1 pc rear o/s door glass outer moulding	nu		150.30	✓
2 pcs rear o/s door top & low hinge	11	@ \$ 79.80	159.60	X
1 pc rear o/s door checker	11		146.70	X
1 pc rear o/s door weatherstrip	nu		152.70	✓
16 pcs rear o/s door trim board clips	11	@ \$ 4.80	76.80	X
1 pc rear o/s door inner lock	11		542.30	X
1 pc o/s rocker panel	nu		386.70	X
1 pc o/s rocker panel Tuff-Kote sticker	11		159.30	X
1 pc rear o/s sport rim	cu7		1,293.30	680 s/w
1 pc rear bumper	nu		482.80	X
1 pc rear bumper o/s side retainer	11		104.40	X
1 pc rear bumper o/s side bracket clips	11		6.90	X
8 pcs rear bumper clips	nu	@ \$ 4.60	36.80	✓
1 pc rear o/s fender	R		928.90	X
6 pcs rear o/s fender inner garnish clips	11	@ \$ 4.60	27.60	X

\$ 8,360.40

Less 25%

\$ 2,090.10

\$ 6,270.30

4 pc rear o/s wheel tyre

380.00 S.M X

To check & adjust wheel balancing & wheel alignment.

150.00 60

To transfer front & rear o/s door trim board, garnish, glass, channel, regulator, motor, hinge, moulding, inner lock, handle, weatherstrip & necessary parts into new door.

300.00 120

To remove & refix carpet, froot mat, garnish, cushion & necessary parts, to enable repair o/s rocker panel, rear o/s fender & o/s centre door pillar panel.

11 120.00 X

To wiring check up for affected wiring system, including door centre locking system.

60.00 30

\$ 7,280.30

Balance C/F.....

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3011/12/20 Your Ref: _____ Date: 5th DEC 2020

MR TAN HOCK GUAN.,

Balance B/F.... \$ 7,280.30

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear o/s fender, o/s rocker panel, o/s centre door pillar panel & necessary parts, to weld, renew & align above parts.

1,900.00 600

To putty & respray painting on all affected accident parts.

2,200.00 1200

To respray Tuff-Kote on all affected accident parts.

150.00 60

To diagnose & re-set rear o/s wheel speed (ABS) sensor & AIR-BAG sensor.

120.00 40

\$ 11,650.30

Dollars : Eleven Thousand Six Hundred Fifty And Cents Thirty Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

P-2 950.20

252

P-22/2-65

SN- 68000

L- 2110.00

5002.65

252

4002