



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8099X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT BUMPER	CRACKED	430.90	430.90
1	FRT BUMPER CTR MOULDING	NOT NECESSARY	188.00	-
1	DAY RUNNING LIGHT RH	NOT NECESSARY	624.50	-
1	FRT BUMPER MOULDING RH	CUT	93.90	93.90
1	FRT BUMPER SIDE SUPT RH	NOT NECESSARY	35.00	-
1	FRT BUMPER SIDE BRKT RH	DEFORMED	28.00	28.00
1	HEADLAMP SUPPORT PANEL	CRACKED	949.30	949.30
1	AIR CURTAIN DUCT RH	NOT NECESSARY	153.80	-
1	ROCKER PANEL GARNISH RH	TO REPAIR SEE LABOUR	290.00	-
1	FRT DOOR RH	BENT	1,797.20	1,797.20
1	FRT DR LWR MOULDING RH	MISSING	186.20	186.20
1	HEADLAMP RH	CRACKED	1,993.65	1,993.65
1	FRT FENDER RH	BENT	588.80	588.80
1	FRT FENDER BLUE-DRIVE RH	NECESSARY	26.60	26.60
1	FRT FENDER SHIELD RH	NOT NECESSARY	164.70	-
1	WING MIRROR RH	CUT	1,391.70	1,391.70
1	FRT WHEEL CAP RH	CUT	346.40	346.40
1	REAR DR LWR MOULDING RH	CUT	166.20	166.20
1	FRT DOOR OTR HANDLE RH	TO REPAIR SEE LABOUR	108.40	-
	LESS 20% DISCOUNT		-1,912.65	-1,599.77
			7,650.60	6,399.08
<u>NETT ITEMS</u>				
1	FRT DOOR COMFORTDELGRO RH (N)	NECESSARY	75.00	75.00
1	REAR DOOR APPS STICKER RH (N)	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-15.50	-15.50
			139.50	139.50

Report Ref No. NS/INC20013399/T1vd3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF ROCKER PANEL GARNISH RH AND FRT DOOR OTR HANDLE RH.		900.00	640.00
	SPRAYPAINT CHARGE.		1,500.00	800.00
	CHECK ALL LIGHTING.		50.00	30.00
	TUFF COAT ON AFFECTED PARTS.		100.00	30.00
	TRANSFER OF DOOR.		120.00	60.00
	WHEEL ALIGNMENT.		120.00	80.00
	R/I AIR CON CONDENSER ETC.		150.00	100.00
			2,940.00	1,740.00
	GRAND TOTAL		10,730.10	8,278.58
RECOMMENDED COST OF REPAIRS (CONFIRMED)				8,278.58

Report Ref No. NS/INC20013399/T1vd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.