

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC3/AIG20013428/AGS3Q2

Date:

31/12/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999993925

Claimant Vehicle No : SML124J**Insured Vehicle No :**

SLB2243A

Date of Loss: 03/12/2020

Nature of Claim:

TP

Claim No:

4032546104SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SML124J**

Make & Model: AUDI A3, 999cc TFSI S TRONIC (LED) (A)

Engine No: CHZC29860

Reg. Date: 30/04/2019 (Man. Year: 2019)

Chassis No:

WAUZZZ8V8KA073869

Colour: Blue

Odometer:

9189 km

Engine Capacity: 999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,013.00	1,555.20	2,457.80	61.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,872.00	0.00	3,872.00	100.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,885.00	1,555.20	6,329.80	80.28
+ GST 7.00/7.00% (S\$)	551.95	108.86	443.09	80.28

Nett Amount (S\$)	8,436.95	1,664.06	6,772.89	80.28
		+ Loss of Use (2.0 x S\$50.00/day) (S\$)	100.00	
		+ Doc/Search Fee (S\$)	7.45	
		Nett Liability (S\$)	1,771.51	

INSPECTION

Date of Assignment: 09/12/2020

Date Inspected: 09/12/2020

Estimated Period of Repair: 2.0 days

Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,944.00 FS	*1,555.20 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	191.00 FS	*- FS
3	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	32.00 FS	*- FS
4	2		*REAR BUMPER LOCKING MEGHANISM	Not Necessary	59.00 FS	*- FS
5	1		*REAR BUMPER SPOILER	Not Necessary	234.00 FS	*- FS
6	1		*REAR REINFORCEMENT BEAM	Not Necessary	565.00 FS	*- FS
7	1		*REAR BUMPER BRACKET -LH	Not Necessary	27.00 FS	*- FS
8	1		*REAR BUMPER BRACKET -RH	Not Necessary	28.00 FS	*- FS
9	2		*REAR PARKING AID SENSOR -INNER/OUTER	Not Necessary	484.00 FS	*- FS
10	4		*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
11	1		*PACKING ADHESIVE	Not Necessary	18.00 FS	*- FS
12	1		*AUDI EMBLEM	Not Necessary	122.00 FS	*- FS
13	1		*A3 INSCRIPTION	Not Necessary	95.00 FS	*- FS
14	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)**4,013.00****1,555.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER REAR PARKING AID CHECK FUNCTION AND RENEW ACCIDENT TO DAMAGE	New	280.00	0.00
2	TO DISMANTLE AND RENEW REAR BUMPER .TO REPAIR REAR LID .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,400.00	0.00
3	TO RESPRAY REAR BUMPER AND REAR LID	New	2,000.00	0.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	0.00
Gross Labour Cost (S\$)			3,872.00	0.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >