

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0953/2020/NS
DATE : 5-Dec-20
WIP : 61356

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SLB 2243 A

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315


OWNER'S NAME : MS MUNIYANDI VANITHA
ADDRESS : BLK 170 STIRLING ROAD
#05-1135
SINGAPORE 140170
TELEPHONE : HP +65 81125764
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1900094367
VEHICLE NO : **SML 124 J**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8 V
MODEL YEAR : 30/4/2019
ENGINE NO : CHZ C29860
CHASSIS NO : WAUZZZ8V8KA073869
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-Dec-20
PLACE OF ACCIDENT : NEAR SERENE CENTRE BUKIT TIMAH
ROAD

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 124]**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 280.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR LID. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,400.00	
3	TO RESPRAY REAR BUMPER AND REAR LID.	\$ 2,000.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 3,872.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 124 J

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 REAR BUMPER <i>Debond</i>		\$ 1,944.00	✓
2 REAR BUMPER FIXING PARTS		\$ 191.00	+
3 REAR BUMPER GUIDE SECTION - LH/RH <i>2</i>	2	\$ 32.00	+
4 REAR BUMPER LOCKING MECHANISM	2	\$ 59.00	+
5 REAR BUMPER SPOILER <i>2</i>		\$ 234.00	+
6 REAR REINFORCEMENT BEAM <i>2</i>		\$ 565.00	+
7 REAR BUMPER BRACKET - LH <i>2</i>		\$ 27.00	+
8 REAR BUMPER BRACKET - RH <i>2</i>		\$ 28.00	+
9 REAR PARKING AID SENSOR - INNER/OUTER <i>2</i>	2	\$ 484.00	+
10 REAR PARKING AID SEAL RING <i>4</i>	4	\$ 14.00	+
11 PACKING ADHESIVE <i>2</i>		\$ 18.00	+
12 AUDI EMBLEM <i>NOT IN</i>		\$ 122.00	+
13 A3 INSCRIPTION <i>2</i>		\$ 95.00	+
14 SUNDRIES		\$ 200.00	?
TOTAL SPARE PARTS	:	\$ 4,013.00	
TOTAL LABOUR CHARGES	:	\$ 3,872.00	
GRAND TOTAL	:	\$ 7,885.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian L
09/12/20

SURVEYED DATE

:

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

not authorized, 02 days

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT