



Exceptional Journeys

INSURANCE CO. : AIG


Supplementary Parts For Registration No.: SMQ 9160 T

	<u>Labour</u>	<u>Cost (\$)</u>
1	Repair rear end panel, rear compartment, tail lamp housing	675.00
2	Respray on tail lamp housing and rear compartment	350.00

	Total	1,025.00
	7% GST	71.75
	Grand total	<u>\$ 1,096.75</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD



LOI AI TING
SENIOR OFFICER - ADMIN
DID : 6568 4556 / 4501
FAX : 6567 5258 / 6565 1240