



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV10251/FONG KOK XIANG, RAYMOND (HONG G Reg No/Reg Date SMM1465M / 19/06/201 Date In/Mileage / 0 Chassis No KNAD6811VL6315057 Engine No G3LCKP059588 Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF Colour/Trim UD CLEAR WHITE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	07/12/2020/ 10:09	QUE	261 / Edwin Caina	25341

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER				1600.00
REPAIR BONNET & LHF FENDER				350 1050.00
E PNT98000 RESPRAY FRT BUMPER, BONNET & LHF FENDER				30.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM				120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				50.00
M SUNDRY SUPPLY FRT NUMBER PLATE WITH CASING				20 30.00
M SUNDRY Sundries	1.00	476.00	20.00	380.80
M COVER-FR BUMPER UPR	1.00	367.00	20.00	293.60
M COVER-FR BUMPER, LWR	1.00	55.00	20.00	44.00
M SKID PLATE-FR BUMPER	1.00	32.00	20.00	25.60
M LIP ASSY-FRONT BUMPER	1.00	96.00	20.00	76.80
M GRILLE-FRONT BUMPER	1.00	324.00	20.00	259.20
M GRILLE ASSY-RADIATOR	1.00	27.00	20.00	21.60
M STRIP-FR BUMPER	1.00	13.00	20.00	10.40
M BRACKET-FR BUMPER SIDE, LH	1.00	64.00	20.00	51.20
M COVER-FR BUMPER FOG LAMP, LH	1.00	1845.00	20.00	1476.00
M LAMP ASSY-HEAD, LH				

SURVEYOR NAME :

SURVEYOR SIGNATURE :

DATE :

REMARKS :

Confirm & Accepted by the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp

Nett 5,519.20
7% GST on 5519.20 386.34
Total Payable 5,905.54

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.