

Surveyor : STEVE LKK
 Claim : AIG OD
 DOA : 02.12.2020
 Emailed : 05.01.2021, 3.30pm
 Date Survey : 16.12.2020

VEHICLE NO : SMM 1465 M
 MODEL : KIA STONIC 1.0 A SX
 WIP : 25341

Material	:	\$	<u>795.20</u>
Labour	:	\$	<u>720.00</u>
Sub-Total	:	\$	<u>1,515.20</u>
	:		<u>-</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>1,215.20</u>
GST 7%	:	\$	<u>85.06</u>
Grand Total	:	\$	<u>1,300.26</u>
Finalise By/Date	:	<u>LOI / 05/01/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 16/12/2020	Cust No/Name	LCV10251/FONG KOK XIANG, RAYMOND (HONG G
	Reg No/Reg Date	SMM1465M / 19/06/2019
	Date In/Mileage	16/12/2020/ 22667
	Chassis/Package	KNAD6811VL6315057 /KC17P
	Engine No	G3LCKP059588
	Make/Model	KIA/STONIC 1.0 A SX BJ3 W SUNROOF
	Colour/Trim	UD CLEAR WHITE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	05/01/2021/ 10:01	BLE	260 / AiTing	25341			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								✓ 200.00
REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER UPPER & LOWER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 350.00
E PNT98000								✓ 30.00
RESPRAY ON FRONT BUMPER, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 120.00
A 54900099								✓ 20.00
CHECK WIRING & ELECTRICAL SYSTEM								-300.00
A 10028901								
CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								
M SUNDRY								
SUNDRIES								
X EXC								
EXCESS								
X COVER-FR BUMPER UPR					1.00	476.00	20.00	380.80
X COVER-FR BUMPER,LWR					1.00	367.00	20.00	293.60
X SKID PLATE-FR BUMPER					1.00	55.00	20.00	44.00
X GRILLE-FRONT BUMPER					1.00	96.00	20.00	76.80
Z TEXT								
AIG OD CLAIM								
DOA : 02.12.20								
SURVEYOR STEVE LKK 16.12.20								
REPAIR 03 DAYS								

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	795.20	Nett	1,215.20
Labour	700.00	7% GST on	1215.20
Standard Menu	0.00		85.06
Specialist Job	0.00	Total Payable	1,300.26
Diagnostics Job	0.00		
Sundry/Others	-280.00		
Total(w/o GST)	1,215.20		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



10/10

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.

M-E-K-01-00-0235

VCI Ver.

02.48

ECU Ver.

M-E-K-01-00-0176

OS Ver.

Android 9