



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO20013444/Uqd3e2 Date: 05/01/2021 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBF 5807B	Veh. Inspected	SMU 6467H
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2003542/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	07/12/2020
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA CAMRY HYBRID (A)	c.c	2487
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	AXVH701039930	Colour	RED
Odometer	26488 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/40 R18	PIRELLI	7 mm
L/H Front Tyre	245/40 R18	PIRELLI	7 mm
R/H Rear Tyre	245/40 R18	PIRELLI	7 mm
L/H Rear Tyre	245/40 R18	PIRELLI	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/12/2020	Inspection Date	07/12/2020
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	