

					CO	FNONDELONG	
Our	Job Re	ef No :	305437504		Engineering		
Date	е		09/12/20		ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969		
FIN	ALIZAT	ION FORM			Fax	: 6546 8156	
То	2		LKK		Fax:		
Attn : MrTAUFIKH							
Vehicle Reg No. SHA3434L				Dar	te of Accident	05/12/20	
The	survey	and estimates of	the repairs of the above-me	entioned vehicle	e are as follow	s:-	
1.	The	repair job shall bil	l to:	AIG		GBJ183D	
2.	The finalized amount shall be:						
	(a) Spare Parts after List discount					\$773.84	
	(b) Labour Charges					\$780.00	
		Total for Part-I	By-Part Repair Cost			\$1,553.84	
	(c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: Final Lumpsum Repair cost			20%	_,		
<b>4</b> .	work	hall treat the abo ing days k you for your ass		We confirm the estimates and finalized amount			
	Signature :			Signature:			
	Name			_		16/12/20	
Tel : 62148315 Date :					ite ::	10/12/20	
or C	Official	Use Only					
		Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks	
. Rental Rate P/Day				YES			
		come Paid		NO			
. Sı	rvey Fe	ees					
LTA Search Fee  Medical Fees (on behalf of driver, if applicable)			\$7.49/\$2.00	15			
Overrun							
lema	ırks:						

## COMFORTDELGRO ENGINEERING PTE LTD

Date: 08.12.2020 Time: 17:28:35

REPAIR ESTIMATE

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

JOB NO
REGN NO
SHA3434L

00000000000

MILEAGE
: 00000000000

383 SIN MING DRIVE

**SINGAPORE SINGAPORE 575717** 

65508755

MILEAGE MAKE MODEL

: TOYOTA : PRIUS HYBRID(G4A)

DATE OF REGN : 15.04.2020
DATE/TIME IN : 07.12.2020 09:30
ACCIDENT DATE : 05.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-0573-A PRIG4 FENDER SUB-ASSY FRO 1 945.30 25.00 708.97

0002 04-01-0302-2297-G PRIG4 EMBLEM SIDE PANEL ( 1 86.50 25.00 64.87

SUB-TOTAL : 773.84

JOB NATURE

0000 PB PANEL BEATING 320.00

0001 SP SPRAYPAINT CHARGE 400.00

0002 17-01 CHECK ALL LIGHTING 30.00

0003 20-00 TUFF COAT ON AFFECTED PARTS. 30.00

SUB-TOTAL : 780.00

TOTAL : 1,553.84

\_\_\_\_\_\_ AUTHORISED : YES / NO

MVA NAME & SIGNATURE SURVEYOR NAME & SIGNATURE

DATE: