



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV11445/THTRUCHELVAM S/O SINGARAVELU Reg No/Reg Date SMP9690K*ECB1/ 07/11/201 Date In/Mileage / 12819 Chassis No KNAF5416ML5059771 Engine No G4FGKH738885 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
LAX00000	Credit	07/12/2020/ 11:56	QUD	247 / DonBong	25370				
Description of Goods / Services									
E PNT88000									1600.00
RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BUMPER /									X 100.00
E PNT88000									80.00
REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK									X 80.00
M SUNDRY									60.00
TOP UP A/CON GAS AND CHECK A/CON SYSTEM									
E PNT88000									800.00
REMOVE AND INSTALL PARKING ASSIST									350 800.00
E PNT98000									50.00
PAINT WORK SPRAY FRONT BUMPER AND AFFECTED PORTION									50.00
M SUNDRY									80.00
SUPPLY FRONT NUMBER PLATE WITH FRAME									X 80.00
M SUNDRY									30.00
PERFORM RUST PREVENTION									30.00
A 54900099									120.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM									120.00
A 10028901									50.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST									20 50.00
M SUNDRY									
SUNDRIES						1.00	675.00	20.00	540.00
M CARRIER ASSY-FRONT END MODULE						1.00	497.00	20.00	397.60
M BEAM COMPLETE-FR BUMPER						1.00	687.00	20.00	549.60
M CONDENSER ASSY-COOLER						1.00	26.00	23.00	20.02
M COOLANT (4L)						1.00	28.00	20.00	22.40
M GUARD-AIR,LH						1.00	28.00	20.00	22.40
M GUARD-AIR,RH						1.00	84.00	20.00	67.20
M ABSORBER-FRONT BUMPER ENERGY						1.00	22.00	20.00	17.60
M BRACKET-FR BUMPER UPR SIDE MTG						1.00	22.00	20.00	17.60
M BRACKET-FR BUMPER UPR SIDE MTG						1.00	14.00	20.00	11.20
M AIR DUCT-FR BUMPER,RH									

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 7B SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV11445/THIRUCHELVAM S/O SINGARAVELU Reg No/Reg Date SMP9690K*ECB1/ 07/11/201 Date In/Mileage / 12819 Chassis No KNAF5416ML5059771 Engine No G4FGKH738885 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	07/12/2020/ 11:56	QUD	247 / DonBong	25370			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	LAMP ASSY-SIDE REPEATER, RH	X	NIN		1.00	143.00	20.00	114.40
M	MOULDING-FRONT BUMPER, RH	X	NIN		1.00	216.00	20.00	172.80
M	GARNISH-RADIATOR GRILLE	X	OR NIN		1.00	38.00	20.00	30.40
M	GRILLE ASSY-RADIATOR	OR			1.00	328.00	20.00	262.40
M	COVER-FR BUMPER	X	OR		1.00	633.00	20.00	506.40
M	GRILLE-FRONT BUMPER	(BACK)	OR		1.00	485.00	20.00	388.00
M	RETAINER-BUMPER SIDE MTG	X	NIN		2.00	1.00	20.00	1.60
M	LAMP ASSY-FRONT FOG, RH	X	NIN		1.00	303.00	20.00	242.40
M	ULTRASONIC SENSOR ASSY-P.A.S	?	X NIN		1.00	163.00	20.00	130.40
M	ULTRASONIC SENSOR ASSY-P.A.S	?	OR		1.00	163.00	20.00	130.40

Estimate

SURVEYOR NAME : Steve (LKK) 7/12/20, 2.00p
 SURVEYOR SIGNATURE : OD-NM Au
 DATE : EXCIS - 1
 REMARKS : P/P
My Bel sy
3 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Confirms & accepted by confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Authorized signatory and company stamp

	Nett	6,614.82
7% GST on	6614.82	463.04
Total Payable		7,077.86

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.