



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 07.12.2020
Emailed : 15.12.2020, 11am
Date Survey : 07.12.2020

VEHICLE NO : SMP 9690 K
MODEL : KIA CERATO 1.6 A GT
WIP : 25370

Material	:	\$	<u>1,952.80</u>
Labour	:	\$	<u>1,030.00</u>
Sub-Total	:	\$	<u>2,982.80</u>
	:		<u>-</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>2,682.80</u>
GST 7%	:	\$	<u>187.80</u>
Grand Total	:	\$	<u>2,870.60</u>
Finalise By/Date	:		<u>LOI / 15/12/2020</u>

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV11445/THIRUCHELVAM S/O SINGARAVELU Reg No/Reg Date SMP9690K*ECB1/ 07/11/2019 Date In/Mileage 07/12/2020/ 12819 Chassis/Package KNAF5416ML5059771 /KC17 Engine No G4FGKH738885 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK
07/12/2020	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	15/12/2020/ 08:57	BLD	260 / AiTing	25370			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 400.00
E PNT88000 REMOVE AND INSTALL FRONT PARKING ASSIST TO FACILITATE REPAIR								✓ 60.00
E PNT98000 RESPRAY ON FRONT BUMPER, AND ALL OTHER AFFECTED PORTIONS TO THE SAME								✓ 350.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								✓ 120.00
M SUNDRY SUNDRIES								✓ 20.00
S SPECIALISTJOB SUPPLY & REPLACE FRONT LICENSE PLATE WITH FRAME								✓ 50.00
X EXC INSURANCE EXCESS								-300.00
X BEAM COMPLETE-FR BUMPER					1.00	? 497.00	20.00	397.60
X ABSORBER-FRONT BUMPER ENERGY					1.00	? 84.00	20.00	67.20
X BRACKET-FR BUMPER UPR SIDE MTG					1.00	✓ 22.00	20.00	17.60
X BRACKET-FR BUMPER UPR SIDE MTG					1.00	✓ 22.00	20.00	17.60
X GRILLE ASSY-RADIATOR					1.00	✓ 328.00	20.00	262.40
X COVER-FR BUMPER					1.00	✓ 633.00	20.00	506.40
X GRILLE-FRONT BUMPER					1.00	✓ 485.00	20.00	388.00
X ULTRASONIC SENSOR ASSY-P.A.S					1.00	? 163.00	20.00	130.40
X WIRING ASSY-BUMPER EXTENSION → Supp					1.00	207.00	20.00	165.60
Z TEXT AIG OD CLAIM DOA : 07.12.20 SURVEYOR STEVE LKK 07.12.20 POLICY NO : 1900235347								
Guarantee Your Warranty, Maintain with Cycle & Carriage!								

Parts	1,952.80		Nett	2,682.80
Labour	960.00	7% GST on	2682.80	187.80
Standard Menu	0.00			
Specialist Job	50.00		Total Payable	2,870.60
Diagnostics Job	0.00			
Sundry/Others	-280.00			
Total(w/o GST)	2,682.80			

This is not an official tax invoice.
 This is a computer generated document, no signature is required.


INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SMP 9690 K**


<u>Materials</u>		<u>Cost (\$)</u>
1	Wiring assy-bumper extension	207.00 ✓ BR
Total		207.00
Less 20% discount		41.40
Total after discount		165.60
7% GST		11.59
Grand total		<u>\$ 177.19</u>

Thank You.

Yours faithfully



LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240



HOME

Online



CERATO/FORTE../2020/G 1.6 MPI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



ICU



CLU



WPC

12/12

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
--------	-----	-------------	-------

No Current DTC

S/W Ver.

M-E-K-01-00-0234

VCI Ver.

02.48

ECU Ver.

M-E-K-01-00-0175

OS Ver.

Android 10