

# XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719

E-mail : xinyaauto@singnet.com.sg

Tel: 6270 3481 Fax: 6278 7522

Date : 07-Dec-20

Address : TNG KIM CHEONG  
BLK 630 WOODLANDS RING ROAD  
#03-226  
SINGAPORE 730630

Reference : TP 1265/12/20  
Vehicle No : SMM 7034J  
Make/Model : TOYOTA ALTIS  
Insurance Co. : NTUC

## RE : QUOTATION TO SMM 7034J FOR THIRD PARTY CLAIMS.

| PARTS REQUIRED              |                                     | QTY | AMT \$ |                   |
|-----------------------------|-------------------------------------|-----|--------|-------------------|
| 1)                          | REAR BUMPER <i>repair</i>           | 1   | \$     | 538.90            |
| 2)                          | REAR BUMPER ENFORCEMENT <i>X</i> NN | 1   | \$     | 389.95            |
| 3)                          | BUMPER RETAINER <i>X</i> NN         | 2   | \$     | 211.20            |
| 4)                          | BUMPER REFLECTOR <i>X</i> NN        | 2   | \$     | 159.00            |
| 5)                          | BUMPER CLIPS <i>X</i> NN            | 10  | \$     | 55.00             |
| LIST PRICE TOTAL            |                                     |     | \$     | 1,354.05          |
| LESS DISCOUNT 25%           |                                     |     | \$     | 338.51            |
| LIST PRICE TOTAL AFTER LESS |                                     |     | \$     | 1,015.54          |
| 6)                          | REVERSE SENSOR <i>X</i> NN          | 1   | \$     | 180.00            |
| NETT PRICE TOTAL            |                                     |     |        | \$180.00          |
| TOTAL PARTS COST            |                                     |     |        | <b>\$1,195.54</b> |

## LABOUR AND MISCELLANEOUS CHARGES

|    |                                                                        |    |                                     |
|----|------------------------------------------------------------------------|----|-------------------------------------|
| 1) | TO REMOVE & REPLACE REAR BUMPER, ENFORCEMENT AND TO PANEL BEAT & ALIGN | \$ | <del>600.00</del> 150<br>(3 DAYS)   |
| 2) | TO PUTTY & SPRAY PAINT REAR BUMPER AND OTHER OTHER AFFECTED AREA.      | \$ | <del>800.00</del> 200<br>(4 PANELS) |
| 3) | TO CHECK & RECTIFY WIRING AND REPLACE REVERSE SENSOR                   | \$ | 100.00 <i>X</i>                     |

### LABOUR TOTAL

*Rahul*  
*Hp 90010068*  
**\$ 1,500.00**

### TOTAL ESTIMATED REPAIR COST

*2 days*  
*22/12/2020*  
*@ 1430*  
*Revy after repair*  
**\$ 2,515.54**

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: