

XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719

E-mail : xinyaauto@singnet.com.sg

Tel: 6270 3481 Fax: 6278 7522

Date : 07-Dec-20

Address : TNG KIM CHEONG
BLK 630 WOODLANDS RING ROAD
#03-226
SINGAPORE 730630

Reference : TP 1265/12/20
Vehicle No : SMM 7034J
Make/Model : TOYOTA ALTIS
Insurance Co. : NTUC

RE : QUOTATION TO SMM 7034J FOR THIRD PARTY CLAIMS.

PARTS REQUIRED		QTY	AMT \$	
1)	REAR BUMPER <i>repair</i>	1	\$	538.90
2)	REAR BUMPER ENFORCEMENT <i>X</i>	1	\$	389.95
3)	BUMPER RETAINER <i>X</i>	2	\$	211.20
4)	BUMPER REFLECTOR <i>X</i>	2	\$	159.00
5)	BUMPER CLIPS <i>X</i>	10	\$	55.00
LIST PRICE TOTAL			\$	1,354.05
LESS DISCOUNT 25%			\$	338.51
LIST PRICE TOTAL AFTER LESS			\$	1,015.54
6)	REVERSE SENSOR <i>X</i>	1	\$	180.00
NETT PRICE TOTAL				\$180.00
TOTAL PARTS COST				\$1,195.54

LABOUR AND MISCELLANEOUS CHARGES

1)	TO REMOVE & REPLACE REAR BUMPER, ENFORCEMENT AND TO PANEL BEAT & ALIGN	\$	600.00 150 (3 DAYS)
2)	TO PUTTY & SPRAY PAINT REAR BUMPER AND OTHER OTHER AFFECTED AREA.	\$	800.00 200 (4 PANELS)
3)	TO CHECK & RECTIFY WIRING AND REPLACE REVERSE SENSOR	\$	100.00 <i>X</i>

LABOUR TOTAL

Rahul
Hp 90010068
\$ 1,500.00

TOTAL ESTIMATED REPAIR COST

2 days
22/12/2020
@ 1430
Revy after repair
\$ 2,515.54

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: