



VAG Singapore Pte Ltd
48 Toh Guan Road East
#05-136, Enterprise Hub
Singapore 608586

Repair Estimate

Tel: 6267 9916
Fax: 6267 9313
www.avantage.sg

Date : 4-Dec-2020

Vehicle Num : SLX8079C

Make/Model : Hyundai Elantra AD 1.6

Chassis No : KMHD841CMJU645950

S/N	PARTS	QTY	PRICE	TOTAL
1	Bonnet <i>bt /</i>	1		\$ 1,017.27
2	LH Hinge <i>? bt /</i>	1		\$ 45.68
3	RH Hinge <i>? xsr</i>	1		\$ 45.68
4	Front Bumper <i>turn /</i>	1		\$ 432.07
5	LH Bracket <i>na /</i>	1		\$ 32.47
6	Front Grille <i>cr /</i>	1		\$ 324.13
7	Front Logo <i>ms /</i>	1		\$ 25.21
8	Top Garnish, Front Grille <i>cr /</i>	1		\$ 72.45
9	Top Strip, Front Grille <i>cut /</i>	1		\$ 39.62
10	LH Headlight <i>cr /</i>	1		\$ 756.96
<i>Supplementary -</i>				
<i>LH Reinforcement, Headlight - cr /</i>				
TOTAL PARTS				\$ 2,791.54
Less 20%				\$ 558.31
TOTAL AMOUNT				\$ 2,233.23
MISCELLANEOUS ITEM				
1	Sundries		\$ 50.00	\$ 20 / 50.00
2	Tuff Kote		\$ 30.00	\$ 30.00
LABOUR				
1	Remove and refit Bonnet, Hinge, Front Bumper, Grille, LH Headlight and other associated components.		\$ 800.00	\$ 500 / 800.00
2	Surface preparation, spray paint and polish Bonnet, Hinge, Front Bumper and other affected areas.		\$ 1,000.00	\$ 500 / 1,000.00
3	Dianostic check and erase fault codes after the repair.		\$ 80.00	\$ 60 / 80.00
<i>Resue - Hp 90010068</i>				
<i>4 days</i>				
<i>43 P/P</i>				
<i>16/12/2020 @ 1230</i>				
TOTAL				\$ 4,193.23
GST 7%				\$ 293.53
GRAND TOTAL				\$ 4,486.76

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4213.39