



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2102193

INV Date 05/04/2021

Reference CC4/LPC20013476/Aps3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMP 1890C

Insured Veh. SLF 3914U

Claim No. 20/20/20/VP05/023973

Policy No.

Accident Date 04/12/2020

Inspection Date 08/12/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC20013476/Aps3q2 Date: 05/04/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLF 3914U	Veh. Inspected	SMP 1890C
	Policy No.		Coverage (\$)	0.00
	Claim No.	20/20/20/VP05/023973	Excess (\$)	0.00
	Assign From	KENNY	Assign Date	07/12/2020
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS ALPHA	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	ZVW400032981	Colour	WHITE
	Odometer	137427 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	KAPSEN	6 mm
	L/H Front Tyre	205/60 R16	KAPSEN	6 mm
	R/H Rear Tyre	205/60 R16	KAPSEN	6 mm
	L/H Rear Tyre	205/60 R16	KAPSEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/12/2020	Inspection Date	08/12/2020
	Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		21 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 1890C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT WINDSCREEN	CRACKED	1,899.30	1,899.30
1	FRONT WINDSCREEN MOULDING	NECESSARY	123.50	123.50
1	FRONT WIPER GARNISH	CUT	580.30	580.30
1	FRONT BONNET	DENTED	988.30	988.30
2	FRONT BONNET HINGE @\$72.30	BENT	144.60	144.60
1	FRONT BONNET LOCK	DAMAGED	144.30	144.30
1	FRONT BONNET INSULATOR	NOT NECESSARY	377.50	-
1	FRONT BONNET ROD STAND	NOT NECESSARY	120.40	-
1	FRONT BONNET ROD STAND HOCK	NOT NECESSARY	50.00	-
1	FRONT BUMPER	DISTORTED	1,288.30	781.00
2	FRONT BUMPER SIDE RETAINER @\$62.40	NECESSARY	124.80	124.80
1	FRONT BUMPER TOP SEAL	NOT NECESSARY	122.20	-
2	FRONT BUMPER INNER SIDE GARNISH @\$130.50	CRACKED	261.00	261.00
1	FRONT BUMPER LOGO	NOT NECESSARY	1,098.60	-
1	FRONT BUMPER CENTRE GRILLE	CRACKED	481.20	481.20
1	FRONT BUMPER LOWER GRILLE	DEFORMED	580.00	580.00
2	FRONT BUMPER LOWER GRILLE FOGLAMP @\$320.00	CRACKED	640.00	640.00
2	FRONT BUMPER LOWER GRILLE TOWING COVER @ \$45.30	DEFORMED	90.60	90.60
1	BONNET LOCK CABLE	NOT NECESSARY	85.00	-
1	AIR -CON PIPE	BENT	325.00	325.00
2	FRONT BUMPER DAY LIGHT @\$588.90	CRACKED	1,177.80	1,177.80
2	FRONT BUMPER DAY LIGHT UPPER GARNISH @\$40.00	NOT NECESSARY	80.00	-
1	FRONT BUMPER REINFORCEMENT	BENT	488.70	488.70
2	FRONT BUMPER REINFORCEMENT BRACKET @\$270.30	BENT	540.60	540.60
1	FRONT BUMPER REINFORCEMENT SPONGE	CRACKED	120.00	120.00
1	FRONT BUMPER NUMBER PLATE HOLDER	DEFORMED	90.00	90.00
1	FRONT BUMPER UNDER COVER	TORN	480.00	280.20
2	HEADLAMP @\$988.30	CRACKED	1,976.60	1,976.60
2	HEADLAMP LOWER BRACKET @\$80.00	CRACKED	160.00	160.00
2	FRONT FENDER @\$850.00	N/S BUCKLED	1,700.00	850.00

Report Ref No. CC4/LPC20013476/Aps3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT FENDER EMBLEM @\$60.00	NECESSARY	120.00	120.00
2	FRONT FENDER INNER PROTECTION @\$130.00	NOT NECESSARY	260.00	-
2	FRONT FENDER INNER COWLING @\$190.00	NOT NECESSARY	380.00	-
2	FRONT QUARTER GLASS @\$210.00	NOT NECESSARY	420.00	-
2	FRONT DOOR @\$1355.60	TO REPAIR SEE LABOUR	2,711.20	-
1	FRONT SUPPORT PANEL	BUCKLED	1,588.30	972.00
1	FRONT SUPPORT PANEL TOP COVER	DEFORMED	140.00	140.00
1	AIR DUCT	NOT NECESSARY	250.00	-
1	AIR CLEANER BOX	CRACKED	1,200.00	968.00
1	ENGINE COVER	CRACKED	160.00	160.00
1	FRONT WHEEL RADIATOR	BENT	988.30	988.30
1	FRONT RADIATOR	BENT	2,144.30	1,317.00
1	FRONT RADIATOR TOP GARNISH	CRACKED	320.00	245.00
2	FRONT RADIATOR TOP GARNISH BRACKET @\$55.20	DAMAGED	110.40	110.40
1	AIR-CON CONDENSOR	BENT	688.90	688.90
2	AIR-CON CONDENSOR AIR GUIDE @\$90.00	CRACKED	180.00	180.00
2	FAN BLADE @\$230.00	DEFORMED	460.00	344.00
1	FAN BLADE HOUSING	CRACKED	320.00	320.00
2	FAN BLADE MOTOR @\$655.30	NOT NECESSARY	1,310.60	-
1	WASHER TANK	NOT NECESSARY	230.00	-
1	DASHBOARD	TORN	1,155.30	1,155.30
1	DASHBOARD AIRBAG	ACTIVATED	3,988.60	3,358.00
1	STEERING WHEEL AIRBAG	ACTIVATED	2,855.30	2,589.00
1	SAFETY BELT (PASSENGER)	ACTIVATED	988.30	898.00
1	SAFETY BELT (DRIVER)	ACTIVATED	988.30	898.00
1	FRONT SEAT AIRBAG (PASSENGER)	ACTIVATED	1,655.30	1,655.30
1	FRONT SEAT AIRBAG (DRIVER)	ACTIVATED	1,855.30	1,855.30
2	FRONT AIRBAG SENSOR @\$380.00	ACTIVATED	760.00	760.00
1	FRONT AIRBAG MODULE	ACTIVATED	1,355.40	1,092.00
1	TOP ROOF CURTAIN	CRUMPLED	3,855.60	2,528.00
2	TOP ROOF CURTAIN AIRBAG @\$1988.70	ACTIVATED	3,977.40	3,977.40
1	TAILGATE	DISTORTED	1,455.90	929.00

Report Ref No. CC4/LPC20013476/Aps3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE LOGO	NECESSARY	72.10	72.10
1	TAILGATE EMBLEM 'PRIUS'	NECESSARY	68.00	68.00
1	TAILGATE EMBLEM 'HYBRID SYNERGY DRIVE'	NECESSARY	60.00	60.00
2	TAILGATE DAMPER @\$280.00	NOT NECESSARY	560.00	-
2	TAILGATE HINGE @\$60.00	NOT NECESSARY	120.00	-
1	TAILGATE LOCK	DAMAGED	360.00	360.00
1	TAILGATE LOCK CATCH	NOT NECESSARY	80.00	-
1	BOOTLID INNER BOARD	CRACKED	530.00	530.00
2	BOOTLID INNER SIDE BOARD @\$230.00	NOT NECESSARY	460.00	-
1	BOOTLID INNER TOP BOARD	NOT NECESSARY	220.00	-
1	BOOTLID INNER HANDLE	NOT NECESSARY	60.00	-
2	TAILGATE STOPPER @\$20.00	NOT NECESSARY	40.00	-
1	TAILGATE WEATHERSTRIPE	CUT	320.00	320.00
1	TAILGATE WINDSCREEN MOULDING	NECESSARY	155.60	155.60
1	SET TAILGATE NUMBER PLATE	DAMAGED	180.00	180.00
1	TAILGATE NUMBER PLATE OUTER GARNISH	CRACKED	420.00	420.00
1	REAR BUMPER	DISTORTED	820.00	524.00
2	REAR BUMPER SIDE RETAINER @\$60.30	NECESSARY	120.60	120.60
2	REAR BUMPER REINREFLECTOR @\$90.00	CRACKED	180.00	180.00
2	TAILLAMP @\$630.00	CRACKED	1,260.00	1,260.00
2	TAILLAMP PANEL @\$350.00	TO REPAIR SEE LABOUR	700.00	-
2	REAR FENDER @\$1115.90	TO REPAIR SEE LABOUR	2,231.80	-
2	REAR FENDER INNER TRIM (LOWER) @\$888.50	CRACKED	1,777.00	1,312.00
2	REAR FENDER AIR VENT @\$90.00	NOT NECESSARY	180.00	-
2	REAR QUARTER GLASS MOULDING @\$90.00	NOT NECESSARY	180.00	-
1	REAR END DPANEL	DISTORTED	630.00	630.00
1	REAR END DPANEL TOP GARNISH	DEFORMED	255.80	255.80
1	REAR FLOOR PANEL	DISTORTED	1,055.90	972.00
1	REAR FLOOR PANEL CENTRE TRAY	CRACKED	630.00	460.00
1	REAR FLOOR PANEL CENTRE TRAY COVER	CRACKED	530.00	530.00
1	REAR FLOOR PANEL SIDE TRAY RH	CRACKED	230.00	230.00
2	REAR FLOOR PANEL SIDE TRAY COVER @\$280.00	CRACKED	560.00	560.00

Report Ref No. CC4/LPC20013476/Aps3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR CHASSIS SUB ASSY @\$280.50	TO REPAIR SEE LABOUR	561.00	-
1	REAR TOOLS SPONGE	CRACKED	280.00	280.00
1	REAR EXHAUST PIPE	BENT	922.30	922.30
2	REAR EXHAUST PIPE MOUNTING @\$105.30	NOT NECESSARY	210.60	-
1	BUMPER LOGO	CRACKED	80.00	80.00
1	REAR EXHAUST PIPE SHIELD HEAT	CRUMPLED	350.00	186.00
	LESS 25% DISCOUNT		-18,165.50	-12,941.28
			54,496.50	38,823.82
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	MISSING	50.00	50.00
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	120.00	60.00
1	ERP STICKER (SN)	NECESSARY	30.00	20.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	20.00	20.00
1	SET HEADLAMP CLIPS (SN)	NECESSARY	20.00	20.00
1	SET FRONT FENDER INNER COWLING CLIPS (SN)	NOT NECESSARY	20.00	-
1	FRONT QUARTER GLASS SEALANT (SN)	N/S NECESSARY	120.00	40.00
1	SET FRONT SUPPORT TOP COVER CLIPS (SN)	NECESSARY	20.00	20.00
1	SET DASHBOARD CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR NUMBER PLATE (SN)	MISSING	50.00	50.00
1	TAILGATE SEALANT (SN)	NOT NECESSARY	120.00	-
1	SET TAILGATE INNER BOARD CLIPS (SN)	NECESSARY	20.00	20.00
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	120.00	60.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	20.00	20.00
2	TAILLAMP SEALANT @\$120.00 (SN)	NOT NECESSARY	240.00	-
2	REAR FENDER SEALANT @\$120.00 (SN)	NOT NECESSARY	240.00	-
1	REAR END PANEL INSULATOR SEAL (SN)	NECESSARY	150.00	60.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	20.00	20.00
1	REAR FLOOR PANEL INSULATOR SEAL (SN)	NECESSARY	150.00	150.00
1	REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
1	REVERSE CAMERA (SN)	NOT NECESSARY	550.00	-
			2,330.00	840.00

Report Ref No. CC4/LPC20013476/Aps3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	PANEL BEATING ,REMOVAL AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF FRONT DOOR .		3,000.00	1,200.00
	TO SPRAY PAINT AFFECTED AREA.		3,000.00	1,400.00
	TUFF COAT.		250.00	80.00
	WIRING CHECK .		180.00	30.00
	TO REMOVE AND REFIX FRONT SAFTLY BELT .		380.00	120.00
	REMOVE AND REFIX FRONT DASHBOARD .		300.00	220.00
	REMOVE AND REFIX FRONT WINDSCREEN .		160.00	120.00
	REMOVE AND REFIX FRONT QUARTER GLASS .		100.00	40.00
	TO REMOVE AND REFIX ALL AIRBAG INCLUDING PROGRAMME.		2,000.00	750.00
	TO REMOVE AND REFIX ROOFTOP CUSHION .		550.00	350.00
	TO REMOVE AND REFIX FRONT PASSENGER /DRIVE SEAT.	NOT NECESSARY	440.00	-
	TO REMOVE AND REFIX FRONT DOOR .	NOT NECESSARY	180.00	-
	PANEL BEATING ,REMOVAL AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL,REAR FENDER AND REAR CHASSIS SUB ASSY.		3,000.00	1,400.00
	TO SPRAY PAINT AFFECTED AREA.		3,000.00	1,400.00
	TUFF COAT.		250.00	100.00
	WIRING CHECK .		180.00	30.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIX FUEL TANK TO FACILITATE REPAIR .	NOT NECESSARY	250.00	-
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		100.00	50.00
	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING.		120.00	50.00
	TRANSFER TAILGATE MECHANISM.		120.00	80.00
	REMOVE AND REFIX REAR WINDSCREEN.		160.00	120.00
	REMOVE AND REFIX REAR QUARTER GLASS .	NOT NECESSARY	120.00	-
	REMOVE AND REFIX REAR EXHAUST PIPE .		220.00	80.00
	REMOVE AND REFIX PHV.		80.00	60.00
			18,260.00	7,680.00
	GRAND TOTAL		75,086.50	47,343.82

Report Ref No. CC4/LPC20013476/Aps3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			37,800.00
---	--	--	------------------

Report Ref No. CC4/LPC20013476/Aps3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. SMP 1890C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMP 1890C

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMP 1890C

RE-INSPECTION

