



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel. 65684555 Fax: 65691056



Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /NG KAI KHUAY Reg No/Reg Date SBB3716P / 13/09/201 Date In/Mileage / 0 Chassis No JMAXTGK1WJZ002613 Engine No 4B40DN9040 Make/Model MIT/ECLIPSE CROSS 1.5 T/C 2WD ELEGA Colour/Trim CO2 BRONZE METALLIC/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	04/12/2020/ 16:59	QUE	261 / Edwin Caina	60386			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 R RENEW LHF FENDER , LHF DOOR & LHR DOOR 450x2								900 2250.00
REPAIR LHR FENDER & RR BUMPER								2100.00
E PNT98000 X RESPRAY FR BUMPER , LHF FENDER , LHF DOOR , LHR DOOR , LHR FENDER & RR BUMPER X								1050 120.00
E PNT88000 REMOVE & REFIT LHF DOOR COMPONENT								120.00
E PNT88000 REMOVE & REFIT LHR DOOR COMPONENT								30.00
M SUNDRY RENEW LHF SPORT RIM & TRANSFER TYRE								30.00
M SUNDRY RENEW LHR SPORT RIM & TRANSFER TYRE								480.00
M SUNDRY SUPPLY LHF SPORT RIM Polish								602-91 480.00
M SUNDRY SUPPLY LHR SPORT RIM (workshop put at part)								30.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM								120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								40 80.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED								80.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR								20 30.00
M SUNDRY Sundries					1.00	599.00	23.00	461.23
M FENDER,FR LH X R					1.00	151.00	23.00	116.27
M MOULDING,FR WHEEL ARCH,LH CUT					1.00	949.00	23.00	730.73
M PANEL ASSY,FR DOOR,LH PD					1.00	119.00	23.00	91.63
M MOULDING,F/DR SASH,UPR LH 1 MC								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /NG KAI KHUAY Reg No/Reg Date S8B3716P / 13/09/201 Date In/Mileage / 0 Chassis No JMAXTGK1WJZ002613 Engine No 4B40DN9040 Make/Model MIT/ECLIPSE CROSS 1.5 T/C 2WD ELEGA Colour/Trim CO2 BRONZE METALLIC/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	04/12/2020/ 16:59	QUE	261 / Edwin Caina	60386			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	MLDG,F/DR WDO BELT LINE,LH	1	X	N/A	1.00	89.00	23.00	68.53
M	GARNISH,FR DOOR,LH	1	X	N/A	1.00	174.00	23.00	133.98
M	GARNISH,FR DOOR SASH,LH	1	X	N/A	1.00	66.00	23.00	50.82
M	PANEL ASSY,RR DOOR,LH	1	X	N/A	1.00	937.00	23.00	721.49
M	MOULDING,R/DR SASH,UPR LH	1	X	N/A	1.00	114.00	23.00	87.78
M	MLDG,R/DR WDO BELT LINE,LH	1	X	N/A	1.00	120.00	23.00	92.40
M	GARNISH,RR DOOR,LH	1	X	N/A	1.00	102.00	23.00	78.54
M	GARNISH,RR DOOR SASH,FR LH	1	X	N/A	1.00	108.00	23.00	83.16
M	GARNISH,RR DOOR SASH,RR LH	1	X	N/A	1.00	49.00	23.00	37.73
M	GARNISH,SIDE SILL,LH	1	X	N/A	1.00	91.00	23.00	70.07
M	MOULDING,R/DOOR PROTECT,LH	1	X	N/A	1.00	105.00	23.00	80.85
M	MOULDING,RR WHEEL ARCH,LH	1	X	N/A	1.00	153.00	23.00	117.81
M	SHIELD,RR WHEEL,FR LH	1	X	N/A	1.00	126.00	23.00	97.02

Estimate

SURVEYOR NAME: Steve CLKK) 7/12/20, 4.00pm

SURVEYOR SIGNATURE: OD - N/A Author

DATE: 6 days

REMARKS: P/P, Rg Bel, Rg

Let Auto Consumers hence notify
confirm & accepted by the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp

7% GST on Net 9,070.04
9070.04
Total Payable 9,704.94

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.