

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

07 DEC 2020

Estimate No. : b1 56785  
Date Estimated : 07/12/2020  
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -  
Ross Phiroze Khan Wong Jian Hao  
Blk 262 Tampines St 21  
#07-268

Singapore 520262

- ACCOUNT - 219  
India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL   | MILEAGE |
|-----------|-------------------|------------|---------|---------|
| SMT9057T  | WBA6V12030ED04960 | 28/09/2018 | 216i GT | 0       |

### DESCRIPTION

Replace front bumper include remove attachment etc

Painting front bumper

To check electrical wiring sys tem at the front section for p  
roper function including adjus tment of headlights.

Sundries

### VALUE

840 1,275.00

934 1,038.00

150 177.00

? 80.00

Total Labour 1: 2,570.00

### DESCRIPTION

FRT BUMPER LH INSERT ?

FRT BUMPER RH INSERT ?

FRT LH SIDE PANEL TOP MOUNTING ?

FRT RH SIDE PANEL TOP MOUNTING ?

LH FOG LAMP SUPPORT ?

LH FINISHER ?

LH MOLDING (SPORT) ?

FRT BUMPER PRIMED PANEL (PMA) repair

LH GRID LATERAL (LINES/PDC) ?

PLAQUE 82MM ?

LH HEADLIGHT LED TECHNOLOGY ?

| DESCRIPTION                          | QTY | PRIC     | VALUE    |
|--------------------------------------|-----|----------|----------|
| FRT BUMPER LH INSERT ?               | 1   | 10.65    | 10.65    |
| FRT BUMPER RH INSERT ?               | 1   | 10.85    | 10.85    |
| FRT LH SIDE PANEL TOP MOUNTING ?     | 1   | 9.80     | 9.80     |
| FRT RH SIDE PANEL TOP MOUNTING ?     | 1   | 9.85     | 9.85     |
| LH FOG LAMP SUPPORT ?                | 1   | 78.00    | 78.00    |
| LH FINISHER ?                        | 1   | 49.90    | 49.90    |
| LH MOLDING (SPORT) ?                 | 1   | 67.00    | 67.00    |
| FRT BUMPER PRIMED PANEL (PMA) repair | 1   | 897.25   | 897.25   |
| LH GRID LATERAL (LINES/PDC) ?        | 1   | 95.05    | 95.05    |
| PLAQUE 82MM ?                        | 1   | 71.60    | 71.60    |
| LH HEADLIGHT LED TECHNOLOGY ?        | 1   | 2,359.75 | 2,359.75 |

Total Parts : 3,659.70

# Performance Motors Limited

\* Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 56785  
Date Estimated : 07/12/2020  
Prepared By : Chua Kee Sin

Page No. : 2 of 5

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL   | MILEAGE |
|-----------|-------------------|------------|---------|---------|
| SMT9057T  | WBA6V12030ED04960 | 28/09/2018 | 216i GT | 0       |

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

|                                                                     |                           |
|---------------------------------------------------------------------|---------------------------|
| Claims OD <u>3rd Party</u> Uninsured losses / Direct Settlement     |                           |
| Regn No. _____                                                      | Claim No. _____           |
| Date & Time <u>28/12/2020 @ 1425</u>                                | Excess S\$ _____          |
| Surveyor's Name <u>Rafid</u>                                        | Sign _____                |
| Surveyor's Tel <u>96060864</u>                                      | Authorised Yes / No _____ |
| Authorised Date _____                                               | Time _____                |
| RESURVEY PARTS PHOTO BY SURVEYOR Yes / No <u>PML</u> Yes / No _____ |                           |
| Surveyor's E-mail _____                                             |                           |
| No. of Working Days Recommend <u>3 days</u>                         |                           |



|                |   |          |
|----------------|---|----------|
| Labour 1       | : | 2,570.00 |
| Parts          | : | 3,659.70 |
| Labour 2       | : | 0.00     |
| Excess         | : | 0.00     |
| Total GST @ 7% | : | 436.08   |
| Grand Total    | : | 6,665.78 |

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*