

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

Registration No : SMT2326M

Chassis No : JHMRU1810JX202543

Model : HRV DX-SIN CVT YM 2018

Owner's Name : TAN YEONG SHENG

Ins Policy No. :

Date of Accident : 3/12/2020

Document No. : SQT20003930 Page 1

Date : 4. Dec 2020

Customer No. : WZF002

Svc Advisor : YOU PO SOON

Engine No : L15B5672551

Date | Time : 4. Dec 2020 8:34:17 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: TAN YEONG SHENG						
	OWNER INSURER: T/MARINE						
	ACC DATE: 3/12/2020						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: MS. FIRST CAP.						
	TP VEH: SHD3829R						
04711-T7A-J00ZZ	FACE,FR.BUMPER <i>DS/OE</i>	1	487.90	25	365.92	25.61	391.53
71140-T7A-J00	BEAM,R.FR.BUMPER UPPER <i>Che</i>	1	32.50	25	24.37	1.71	26.08
71190-T7A-J00	BEAM,L.FR.BUMPER UPPER <i>11</i>	1	32.50	25	24.37	1.71	26.08
71193-T7A-J00	SPACER,R.FR.BUMPER SIDE <i>11</i>	1	11.30	25	8.47	0.59	9.06
71198-T7A-J00	SPACER,L.FR.BUMPER SIDE <i>11</i>	1	11.30	25	8.47	0.59	9.06
91505-TM8-003	CLIP,BUMPER <i>ner</i>	22	2.30	25	37.95	2.66	40.61
71130-T7A-J00ZZ	BEAM COMP,FR.BUMPER <i>Bert</i>	1	249.50	25	187.12	13.10	200.22
71105-T7A-J10	GARNISH,R.FR.FOG LIGHT <i>11</i>	1	24.90	25	18.67	1.31	19.98
71121-T7A-G01	BASE,FR.GRILLE <i>scr</i>	1	224.30	25	168.22	11.78	180.00
75700-T5A-000	EMBLEM H <i>ner</i>	1	16.40	25	12.30	0.86	13.16
90301-ST0-003	NUTPUSH 3MM <i>ner</i>	2	2.10	25	3.15	0.22	3.37
Sum Item					859.01	60.14	919.15
BOSUN	SUNDRIES <i>ner</i>	1	50.00	20	50.00	3.50	53.50
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	150.00	120	150.00	10.50	160.50
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	1200.00	650	1200.00	84.00	1284.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1200.00	700	1200.00	84.00	1284.00
Sum Labor					2600.00	182.00	2,782.00

Printed on 4/12/2020 10:36:27 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SMT2326M

Chassis No : JHMRU1810JX202543

Model : HRV DX-SIN CVT YM 2018

Owner's Name : TAN YEONG SHENG

Ins Policy No. :

Date of Accident : 3/12/2020

Document No. : SQT20003930 **Page** 2

Date : 4. Dec 2020

Customer No. : WZF002

Svc Advisor : YOU PO SOON

Engine No : L15B5672551

Date | Time : 4. Dec 2020 8:34:17 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
------	-------------	-----	------------	--------	--------	---------------	------------------

Survey By

Marcus Ng

Date & Time

9/12/20 @ 9am.

Excess

—

Status

not Authorised

Signature

Lump sum to be paid.

3 days.

Total Amount	3,459.01	242.14	3,701.15
---------------------	----------	--------	----------

Total (Inclusive of GST)	3,701.15
---------------------------------	-----------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 4/12/2020 10:36:27 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.