LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AIG20013493/GTF3E2

Date:

05/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2070153792

Claimant Vehicle No

GBD3742C

Insured Vehicle No: GBK7304X

Date of Loss: 03/12/2020

Nature of Claim: TP

Claim No: 8552916559SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

Colour:

GBD3742C

Make & Model:

NISSAN NV350, 2.5 PANEL VAN 5AT 5DR (A)

Engine No: Chassis No:

Pre-accident Condition:

YD25355132A JN1MC2E26Z0003018

Yes

Reg. Date: 26/09/2014 (Man. Year: 2014)

Odometer:

210737 km

Engine Capacity:

Grey 2488 cc

Market Value/New Car Price:

N/A Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Sum Insured (S\$):

Steering (Serviceable): Yes Footbrake (Serviceable):

Nο

Handbrake (Serviceable): Yes Engine Modification:

CONDITION OF TYRES

Front Tyre Size:
Front Left Side:
Front Right Side:

195R15 CST 6 mm CST 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 195R15

CST 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date Inspected:

Adjuster:

Date of Assignment:

07/12/2020

23/12/2020

Inspected At:

JI Auto Services Pte Ltd (HQ)

Blk 3006 UBI ROAD 1 #01-346

Singapore 408700

Estimated Period of Repair:

2.0 days

XING GUO QIANG

Manager:

DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH SLIDING DOOR	Buckled	0.00 F	*- F
2	1		*RH BODY PANEL	Repair	0.00 F	*- F
F=Fra	anchise	part.		Total Parts (S\$)	0.00	0.00
			Report was	unsubmitted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >