

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20013497/KTF3Q2

Date: 07/01/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29146780QMY

Claimant
Vehicle No : SMG5554U

Insured Vehicle No : SLG5655Z

Date of Loss: 06/12/2020

Nature of Claim: TP

Claim No: 631693

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMG5554U**

Make & Model: OPEL INSIGNIA GRANDSPORT B16DTH, 1.6 Turbo (A)

Engine No: A2172908GKCX0228

Reg. Date: 26/12/2018 (Man. Year: 2018)

Chassis No: W0VZM6EF0J1070854

Colour: Metallic Brown

Odometer: 126901 km

Engine Capacity: 1598 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45R18

Rear Tyre Size: 245/45R18

Front Left Side: Grenlander 8 mm

Rear Left Side: Grenlander 8 mm

Front Right Side: Grenlander 8 mm

Rear Right Side: Grenlander 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,012.28	1,685.88	3,326.40	66.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,180.00	1,020.00	46.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,212.28	2,865.88	4,346.40	60.26
Approved Total (Overridden) (S\$)		2,300.00		
(S\$)	7,212.28	2,300.00	4,912.28	68.11
+ GST 7.00/7.00% (S\$)	504.86	161.00	343.86	68.11
Nett Amount (S\$)	7,717.14	2,461.00	5,256.14	68.11

INSPECTION

Date of Assignment: 08/12/2020

Date Inspected: 08/12/2020 Inspected At:

Munich Autocare Pte Ltd (HQ)
60 Jalan Lam Huat, #02-02/03 Carros
Centre
Singapore 737869

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jan 2021)
Parts:	143	OPEL INSIGNIA GRANDSPORT B16DTH 1.6 Turbo (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG5554U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*39125440-FENDER,RH	Bent	716.40 FL	*716.40 FL
2	1		*13312747-18 WHEEL	Dented	426.00 FL	*426.00 FL
3	1		*39186445-TYRE SENSOR	Serviceable	181.20 FL	*- FL
4	1		*39159652-FRONT BUMPER	Repair	1,558.80 FL	*- FL
5	1		*13491089-SIGNAL INDICATOR,RH	Scratched	27.60 FL	*27.60 FL
6	1		*39186970-WING MIRROR ASSY,RH	Dented/Cut	616.80 FL	*616.80 FL
7	1		*39081047-WING MIRROR COVER,RH	Dented	86.40 FL	*86.40 FL
8	1		*39171972-FRONT DOOR ASSY,RH	Repair	1,956.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,569.20	1,873.20
- List Item Discount on L Items 10.00/10.00% (\$\$)	556.92	187.32
Total Parts (\$\$)	5,012.28	1,685.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR REPLACING/REPAIRING DAMAGED PARTS AS PER ESTIMATE	New	1,000.00	500.00
2	SPRAY PAINTING FOR-FRONT BUMPER-FRONT RIGHT FENDER-FRONT RIGHT DOOR-WING MIRROR COVER,RH	New	1,200.00	680.00
Gross Labour Cost (\$\$)			2,200.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >