

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 10 Dec 2020

Preliminary Advice

Insured Vehicle No : SLG5655Z
TP Vehicle No : SMG5554U Accident Date : 06/12/2020
Make : OPEL INSIGNIA GRANDSPORT B16DTH Assignment Date : 08/12/2020
Date of Inspection : 08/12/2020 Est. Duration of Repair : 4
Inspection At : MUNICH AUTOCARE PTE LTD (HQ)
60 JALAN LAM HUAT, #02-02/03 CARROS CENTRE
SINGAPORE 737869

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,212.28
Revised Amount	:S\$	2,865.88
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,865.88

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

- () The above survey was conducted on a 'without prejudice' basis.