

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
--	---

Attn: Chhia Nyuk Pui

Date: 25 Jun 2021

Preliminary Advice

Insured	: SLF4837C		
Vehicle No			
TP Vehicle No	: SHA3747J	Accident Date	: 05/12/2020
Make	: TOYOTA PRIUS	Assignment Date	: 08/12/2020
Date of Inspection	: 09/12/2020	Est. Duration of Repair	: 9
Inspection At	: BIFROST AUTO PTE LTD (SIN MING) (HQ) BLK 9 SECTOR C, #01-42 SIN MING INDUSTRIAL ESTATE SINGAPORE 575644		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 26,458.86
Revised Amount	:S\$ 10,,575.83
Check Items (Estimated)	:S\$ 0.00
Total	:S\$ 10,575.83

Lump Sum Repair	:S\$ 8,450.00
-----------------	---------------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value :S\$

Margin for Repair :S\$

Remarks

() The vehicle is economical for repair

() The vehicle is not economical for repair

() Part-by-Part repair

(X) Lump Sum repair

(X) The above survey was conducted on a 'without prejudice' basis.