



Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

RASHSEYD BIN MOHAMAD
 BLK 216B COMPASSVALE DRIVE #06-546
 SINGAPORE 542216

Attention : THE OWNER
 Contact : 84183987

*Not Not have
 11 Imp @ 5900/hr
 Repair After Paint
 5 days*

Estimate : ES007103

Date : 07/12/2020
 Vehicle Num. : SLA6407Z
 Make/Model : NISSAN X-TRAIL 2.0-2016
 Chassis/Eng# : JN1JANT32Z0001532/MR20825168B
 Accident Date : 06/12/2020
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		NETT ITEMS :		4,380.00
1.	1	TAIL GATE <i>CM</i>		126.00
2.	1	TAIL GATE W/SCREEN MOULDING TOP <i>✓</i>		89.50
3.	1	TAIL GATE W/SCREEN MOULDING BOTTOM <i>✓</i>	86.00	172.00
4.	2	TAIL GATE W/SCREEN MOULDING SIDE <i>✓</i>		693.50
5.	1	REAR BUMPER <i>Buc 1/2</i>		469.10
6.	1	REAR BUMPER TOP CHROME <i>✓</i>	38.90	77.80
7.	2	REAR BUMPER SIDE RETAINER <i>✓</i>	195.60	391.20
8.	2	REAR BUMPER BRACKET <i>x R</i>	5.50	44.00
9.	8	REAR BUMPER CLIP <i>✓</i>		596.40
10.	1	REAR BUMPER BEAM <i>x R</i>		147.50
11.	1	REAR BUMPER SPONGE <i>x R</i>		487.50
12.	1	REAR END PANEL <i>x R</i>		492.80
13.	1	REAR END PANEL TOP GARNISH <i>x R</i>		211.00
14.	1	REAR FENDER GARNISH R/H <i>x R</i>		211.00
15.	1	REAR FENDER GARNISH L/H <i>x R</i>		385.00
16.	1	REAR END PANEL LOWER <i>✓</i>		135.00
17.	1	REAR BUMPER CENTRE GRILLE <i>CM</i>		9,109.30
		Nett Total S\$:		910.93
		10.00% Discount S\$:		8,198.37
		SPECIAL NETT ITEMS :		
1.	1	TAIL GATE W/SCREEN SEALANT <i>✓</i>	280.00	226.10
2.	4	REVERSE SENSOR <i>✓</i>		1,120.00
3.	1	REAR NUMBER PLATE <i>✓</i>		25.00
		Special Nett Total S\$:		1,371.10

CONTINUE / ...



Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

RASHSEYD BIN MOHAMAD
 BLK 216B COMPASSVALE DRIVE #06-546
 SINGAPORE 542216

Estimate : ES007103

Attention : THE OWNER
 Contact : 84183987

Date : 07/12/2020
 Vehicle Num. : SLA6407Z
 Make/Model : NISSAN X-TRAIL 2.0-2016
 Chassis/Eng# : JN1JANT32Z0001532/MR20825168B
 Accident Date : 06/12/2020
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :
 SPRAY PAINT DAMAGED AREA AFFECTED
 RUST PROOFING TREATMENT
 TRANSFER TAILGATE COMPONENT TO NEW GATE
 CHANGE TAIL LAMP AND CHECK WIRING
 REMOVE & REINSTALL REAR W/SCREEN GLASS
 TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR
 CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS

750l 1,600.00
 nnw 100.00 X
 60l 150.00
 20l 65.00
 120l 180.00
 1,200.00 500l

 3,295.00

Labour Total S\$:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

SingDollars : Twelve Thousand Eight Hundred Sixty-Four & Cents Forty-Seven Only

Total S\$: 12,864.47
 =====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

RASHSEYD BIN MOHAMAD
 BLK 216B COMPASSVALE DRIVE #06-546
 SINGAPORE 542216

Attention : THE OWNER
 Contact : 84183987

Estimate : ES007103

Date : 07/12/2020
 Vehicle Num. : SLA6407Z
 Make/Model : NISSAN X-TRAIL 2.0-2016
 Chassis/Eng# : JN1JANT32Z0001532/MR20825168B
 Accident Date : 06/12/2020
 Claim No. :
 Reference :
 Policy No. :

*Not Authorized
 L1 Day @
 Resurvey After Paint
 5-6 days*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	TAIL GATE		
3.	1	TAIL GATE W/SCREEN MOULDING TOP		
4.	2	TAIL GATE W/SCREEN MOULDING BOTTOM		
5.	1	TAIL GATE W/SCREEN MOULDING SIDE		
6.	1	REAR BUMPER		
7.	1	REAR BUMPER TOP CHROME		
8.	2	REAR BUMPER SIDE RETAINER		
9.	2	REAR BUMPER BRACKET		
10.	8	REAR BUMPER CLIP		
11.	1	REAR BUMPER BEAM		
12.	1	REAR BUMPER SPONGE		
13.	1	REAR END PANEL		
14.	1	REAR END PANEL TOP GARNISH		
15.	1	REAR FENDER GARNISH R/H		
		REAR FENDER GARNISH L/H		

List Total S\$:
~~2500~~% Discount S\$:

1.	1	SPECIAL NETT ITEMS :		
2.	4	TAIL GATE W/SCREEN SEALANT		
		REVERSE SENSOR		
Special Nett Total S\$:				

LABOUR :
 SPRAY PAINT DAMAGED AREA AFFECTED

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

RASHSEYD BIN MOHAMAD
 BLK 216B COMPASSVALE DRIVE #06-546
 SINGAPORE 542216

Estimate : ES007103

Attention : THE OWNER
 Contact : 84183987

Date : 07/12/2020
 Vehicle Num. : SLA6407Z
 Make/Model : NISSAN X-TRAIL 2.0-2016
 Chassis/Eng# : JN1JANT32Z0001532/MR20825168B
 Accident Date : 06/12/2020
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		RUST PROOFING TREATMENT		100.00 ?
		TRANSFER TAILGATE COMPONENT TO NEW GATE	601	150.00
		CHANGE TAIL LAMP AND CHECK WIRING	201	65.00
		REMOVE & REINSTALL REAR W/SCREEN GLASS	1201	180.00
		TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS		1,200.00 ?
		Labour Total S\$:		<u>3,295.00</u>

SingDollars : Four Thousand Four Hundred Fifteen Only

Total S\$: 4,415.00

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun