

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20013506/UPA3Q2
Date: 29/03/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	FBB8785G	Insured Vehicle No :	SHC2291C
Date of Loss:	09/11/2020	Nature of Claim:	TP
		Claim No:	MCT20110139

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBB8785G	Engine No:	4S3001522
Make & Model:	YAMAHA X-1R, 135cc (M)	Chassis No:	4S3001522
Reg. Date:	28/08/2007 (Man. Year: 2007)	Odometer:	36884 km
Colour:	Blue		
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80-90-17	Rear Tyre Size:	90-80-17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Timsun 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,416.00	924.70	2,491.30	72.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	890.00	310.00	580.00	65.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,306.00	1,234.70	3,071.30	71.33
Approved Total (Overridden) (S\$)		900.00		
Nett Amount (S\$)	4,306.00	900.00	3,406.00	79.10
+ Loss of Use (4.0 x S\$25.00/day) (S\$)		100.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		50.00		
Nett Liability (S\$)		1,057.45		

INSPECTION

Date of Assignment:	07/12/2020	
Date Inspected:	08/12/2020	Inspected At: Sanfu Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6, #02-43 Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	3.0 days	

3/29/2021

Adjuster Report

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 03 Mar 2021)	
Parts:	N/A	YAMAHA X-1R 135cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBB8785G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BAR END	Bent	128.00 F	*128.00 FL
2	1		*R/H HANDLE BAR	Bent	134.00 F	*134.00 FL
3	1		*FRONT METER COVER COWLING	Cut	58.00 F	*58.00 FL
4	1		*FRONT FENDER	Cut	65.00 F	*65.00 FL
5	1		*R/H BRAKE LEVER	Bent	38.00 F	*38.00 FL
6	1		*L/H CLUTCH LEVER	Bent	39.00 F	*39.00 FL
7	1		*L/H HEAD COWLING	Cut	134.00 F	*134.00 FL
8	1		*L/H SIDE FRONT COWLING	Repair	134.00 F	*- FL
9	1		*R/H SIDE FRONT COWLING	Cut	134.00 F	*134.00 FL
10	1		*L/H REAR SIDE COVER	Repair	134.00 F	*- FL
11	1		*L/H GEAR LEVER	Bent	90.00 F	*90.00 FL
12	1		*L/H RIDER FOOTPEG	Cut	113.00 F	*113.00 FL
13	1		*L/H ENGINE CASE	Not Necessary	899.00 F	*- FL
14	1		*HANDPHONE HOLDER	Not Necessary	126.00 F	*- FL
15	1		*REAR SWING ARM	Not Necessary	767.00 F	*- FL
16	1		*STEERING CONE & BEARING	Necessary	120.00 FS	*75.00 FS
17	1		*FRONT NO.PLATE	Scratched	12.00 FS	*10.00 FS
18	1		*REAR NO.PLATE (BENT)	Not Consistent With The Impact	18.00 FS	*- FS
19	1		*BOX	Serviceable	273.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,416.00	1,018.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	93.30
Total Parts (\$\$)	3,416.00	924.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	FRONT FORK ALIGNMENT	New	220.00	60.00
2	WHEEL ALIGNMENT	New	120.00	0.00
3	FRAME ALIGNMENT	New	200.00	0.00
4	WORKMANSHIP TO RENEW DAMAGE PARTS & AREAS	New	350.00	250.00
Gross Labour Cost (\$\$)			890.00	310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >