

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey the repairer's estimate
- To display the repairer's estimate
- Parts price to be based on the resurvey
- Third party survey to be on "Without Prejudice" basis
- No insurance claim to be made
- Supplier to be approved by the resurveyed and is subject to final approval from Insurance Company

SANFU
Motor Pte Ltd

Not Authorized
LKK
8/12/20
1/5 \$900/-
To be phd. After repair
MP90096608

3 days

ASSESSMENT FOR REPAIR : FBB8785G (Signed by Repairer)

YAMAHA X-1R

COE EXPIRY : 27 Aug 2022

Signature:
Date:

Lump Sum / ~~Part by Part~~

Qty Description

1	BAR END	Bent ✓
1	R/H HANDLE BAR	Bent ✓
1	FRONT METER COVER COWLING	cut ✓
1	FRONT FENDER	cut ✓
1	R/H BRAKE LEVER	Bent ✓
1	L/H CLUTCH LEVER	Bent ✓
1	L/H HEAD COWLING	cut ✓
1	L/H SIDE FRONT COWLING	Rx
1	R/H SIDE FRONT COWLING	cut ✓
1	L/H REAR SIDE COVER	Rx
1	L/H GEAR LEVER	Bent ✓
1	L/H RIDER FOOTPEG	cut ✓
1	L/H ENGINE CASE	11x
1	HANDPHONE HOLDER	11x
1	REAR SWING ARM	11x

Repairer's 1st Repair Final
Estimate Survey Survey Survey

128.00			
134.00			
58.00			
65.00			
38.00			
39.00			
134.00			
134.00			
134.00			
134.00			
90.00			
113.00			
899.00			
126.00			
767.00			

2,993.00

Special Nett Items

STEERING CONE & BEARING	hu ✓	75
FRONT FORK ALIGNMENT	60	
WHEEL ALIGNMENT	11x	
FRAME ALIGNMENT	11x	
FRONT NO. PLATE	scr 10	
REAR NO. PLATE	Bent 11x	
BOX	su	x

120.00			
220.00			
120.00			
200.00			
12.00			
18.00			
273.00			

963.00

Total Parts

3,956.00

Labour Charges

- 1 Workmanship to renew damage parts & areas

350.00

350.00

Total Parts & Labours Concluded

4,306.00

p-933
102
839.7

SANFU MOTOR PTE LTD

Company Reg No.: 200612487G

1 Kaki Bukit Ave 6, #02-43, AutoBay@Kaki Bukit, Singapore 417883

Direct Line: 9061 3299 Tel: (65) 6744 7753 Fax: (65) 6744 6010

Email: sanfumotor0243@gmail.com