

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0952/2020/NS
DATE : 5-Dec-20
WIP : 61206

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Rasul

12 days exclude 2 Sundays

jb 8 Feb 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MDM ANG KIAM HOON, SHIRLEY
ADDRESS : 2 FABER PARK
SINGAPORE 129093
TELEPHONE : HP +65 93889556
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO :
VEHICLE NO : **SDB 7377 J**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 27/8/2019
ENGINE NO : CHZ C32050
CHASSIS NO : WAUZZZ8V3KA109760
MILEAGE : 32956KM
DATE IN : 3-Dec-20
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 2-Dec-20
PLACE OF ACCIDENT : LEFT EXIT LANE OUT OF AYE INTO
JURONG TOWN HALL

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDB 7377 J

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY. <i>(Lock carrier replaced)</i>	S/N \$	360.00	360
2	TO DISLODGE ENGINE ASSY WITH GEARBOX ASSY TO FACILITATE THE RENEWAL OF GEARBOX ASSY.	S/N \$	2,800.00	\$ 2,800.00
3	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME. INSPECT AND RENEW ACCORDINGLY.	S/N \$	2,400.00	
4	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00	\$ 500.00
TOTAL LABOUR CHARGES		:	\$ 6,610.00	\$ 3,660.00

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDB 7377 J

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
5	TO RESPRAY FRONT BUMPER.	<i>c/f</i>	\$ 900.00	\$	3,660.00 550.00
6	TO RENEW BOTH FRONT RIMS. TO CARRY OUT PRE AND POST WHEEL ALIGNMENT CHECK.	S/N	\$ 560.00		
7	TO TOW BACK VEHICLE FROM ACCIDENT SCENE.	S/N	\$ 280.00		
8	Added labours (14 Dec)		\$ 4,000.00	\$	2,450.00
8a	Added labours (26 Jan 21)	S/N	\$ 1,800.00	\$	1,800.00
9	TO CARRY OUT PRE AND POST REPAIR DISGNOCTIC CHECK.	S/N	\$ 384.00	\$	384.00
TOTAL LABOUR CHARGES		:	\$ 14,534.00	\$	8,844.00

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDB 7377 J

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
5	TO RESPRAY FRONT BUMPER.	<i>c/f</i>	\$ 900.00	\$	3,660.00 550.00
6	TO RENEW BOTH FRONT RIMS. TO CARRY OUT PRE AND POST WHEEL ALIGNMENT CHECK.	S/N	\$ 560.00		
7	TO TOW BACK VEHICLE FROM ACCIDENT SCENE.	S/N	\$ 280.00		
8	Added labours (14 Dec)		\$ 4,000.00	\$	2,450.00
8a	Added labours (26 Jan 21)	S/N	\$ 1,800.00	\$	1,800.00
9	TO CARRY OUT PRE AND POST REPAIR DISGNOCTIC CHECK.	S/N	\$ 384.00	\$	384.00
TOTAL LABOUR CHARGES		:	\$ 14,534.00	\$	8,844.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDB 7377 J

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER		\$	1,987.00	
2	FRONT BUMPER FIXING PARTS		\$	185.00	
3	FRONT BUMPER GRILLE - CENTRE		\$	159.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$	530.00	\$ 424.00
5	RADIATOR GRILLE		\$	1,406.00	
6	RADIATOR GRILLE CLOSING ELEMENT		\$	189.00	
7	AIRCON STICKER	NEC	\$	8.00	
8	CAUTION SIGN STICKER	NEC	\$	14.00	
9	NOISE INSULATION		\$	264.00	\$ 210.80
10	FRONT ALUMINIUM RIM	2	\$	1,397.00	
11	STABILIZER BAR		\$	384.00	
12	ASSEMBLY CARRIER		\$	972.00	
13	BONDED RUBBER BUSH SET		\$	103.00	
14	PENDULUM SUPPORT		\$	88.00	
15	GEARBOX SUPPORT - LH/RH	2	\$	44.00	
16	STEERING GEAR		\$	4,548.00	
17	7-SPEED DUAL CLUTCH GEARBOX		\$	16,680.00	\$ 13,344.00
18	TRANSMISSION FLUID		\$	60.00	
19	GEARBOX MOUNTING - LH		\$	249.00	
20	GEARBOX CONSOLE - LH		\$	184.00	
SUB TOTAL SPARE PARTS		:	\$	29,451.00	\$ 13,978.80

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDB 7377 J

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		
			S/NETT	REMARKS	
		<i>c/f</i>		\$	13,978.80
21	ENGINE MOUNTING		\$ 246.00		
22	FRONT NO PLATE	S/N	\$ 60.00		
24	SUPPLEMENTARY		\$ 2,272.00	\$	1,817.04
25	SUNDRIES		\$ 400.00	\$	163.52
TOTAL SPARE PARTS		:	\$ 32,429.00	\$	15,959.36
TOTAL LABOUR CHARGES		:	\$ 14,534.00	\$	8,844.00
GRAND TOTAL		:	\$ 46,963.00	\$	24,803.36

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

BL-25/01/21



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate 2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0952/2020/NS 14-Dec-20 George Wong 1 of 1 SDB 7377 J AUDI A3 SEDAN 1.0 TFSI 8V	
Quantity	Description		Unit Price	Amount
<u>Parts</u>				
1	FRONT LOCK CARRIER WITH MOUNTING		\$ 719.00	\$ 575.20
2	READY MIX COOLANT	4	\$ 177.00	\$ 141.44
3	A/C CONDENSER		\$ 517.00	\$ 413.20
4	ADDITIONAL RADIATOR		\$ 859.00	\$ 687.20
				\$ 1,817.04
<u>Labour</u>				
1	To remove and renew aircon condenser, additional radiator, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	\$ 1,200.00	\$ 1,200.00
2	To renew front lock carrier and align to position.		\$ 2,800.00	\$ 1,250.00
				\$ 2,450.00
GRAND TOTAL			\$ 6,272.00	\$ 4,267.04

For Premium Automobiles Pte Ltd

Authorised Signature